





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T30 TDI P/V
Colour	Silver
Year of manufacture	2011
Top speed	98 mph
0 - 60 mph	16.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	101 BHP
	101 5111
Max. torque	250 Nm at 2.500 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	40.9 mpg
Consumption combined	35.8 mpg



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-07-05

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-01-17
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	14
Total items failed	2

MOT #12	2024-01-15 14:48
MOT test number	927757244535
Result	✓ Passed
Next expiry date	2025-01-17

MOT #11	2023-01-18 09:47
MOT test number	593032294665
Result	✓ Passed

MOT #10	2023-01-13 12:28
MOT test number	194723310541
Result	X Failed
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) Advice Offside Front Service brake binding but not excessively (1.2.1 (f))	

MOT #9	2022-01-14 13:44
MOT test number	300680970199
Result	✓ Passed

CarCheck.co.uk page 3/12



SM11VKU

report date: 2024-03-29

MOT #8

MOT test number

506570094044

Result

Advice Wiper blades worn

Advice Exhaust system corroded

MOT #7

MOT test number

615931567489

Result

Advice Under trays fitted obscuring some under vehicle components

MOT #6

MOT test number

469885387433

Result

Advice Under trays fitted obscuring some under vehicle components

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #5

MOT test number

Result

Advice

Under trays fitted obscuring some under vehicle components

2018-06-11 11:48

106124067371

✓ Passed

MOT #4

MOT test number

Result

Advice Under trays fitted obscuring some under vehicle components.

2017-05-31 08:11

139249119579

✓ Passed

CarCheck.co.uk page 4/12



Result

SM11VKU report date: 2024-03-29

Passed

MOT #3 2016-06-27 08:01

MOT test number 746397669872

Result ✓ Passed

Advice Tyre worn close to the legal limit BOTH REAR TYRES BECOMING LOW ON TREAD, APPROX 2/3 MM ON BOTH (4.1.E.1)

Advice Centre Exhaust has a minor leak of exhaust gases SILENCER OUTER SKIN SPLITTING (7.1.2)

MOT #2

MOT test number

Result

Notice Under-trays fitted obscuring some underside components

2015-06-10 08:29

325041865172

✓ Passed

 MOT #1
 2014-06-11 11:13

 MOT test number
 486572764104

Notice Engine covers fitted obscuring some components in the engine bay

Notice Slight bind on f/o/s brake

Notice Under-trays fitted obscuring some underside components

Notice Front tyres scrubbing off on inner edges

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status

Days left

63

MOT expiry date

17 January 2025

Full MOT history

See MOT history

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date
Category

Type

Damage 2

Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dov here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NIK NIK
Plate since	
Current registration	UK ZIS
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



SM11VKU

report date: 2024-03-29

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-06-30
Last registration	2024-01-15
Complete history	See info



Registration #1	2011-06-30	20 mi
Registration #2	2014-06-11	24.978 mi
Registration #3	2015-06-10	29.582 mi
Registration #4	2016-06-27	37.365 mi
Registration #5	2017-05-31	39.587 mi
Registration #6	2018-06-11	43.712 mi
Registration #7	2019-06-03	45.048 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		0.00 44
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	2476 mm
Length	5292 mm
Kerb weight	1912 kg

Additional information

CarCheck.co.uk page 12/12