



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA VTX 16V PICASSO
Colour	Grey
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	135 g/km
CO2 label	E






Internet history

Entry 2


Date	2023-01-22
Pictures	13
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-08-15
Pictures	22
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-05-14
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	7
Total items failed	8

MOT #15	2023-05-15 15:23
MOT test number	396165597612
Result	✓ Passed
Next expiry date	2024-05-14

MOT #14	2023-05-15 14:00
MOT test number	765621749665
Result	✗ Failed
Fail	Offside Rear Passenger's seat insecure (6.2.6 (a) (ii))
Fail	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Minor	Tyre obviously under inflated spare tyre (5.2.3 (I))
Fail	Offside Rear Seat belt not functioning as intended (7.1.2 (c))
Minor	Nearside Rear Tyre obviously under inflated (5.2.3 (I))

MOT #13	2022-08-03 10:09
MOT test number	563999025220
Result	✓ Passed
Advice	All tyres cracked/perished

**MOT #12** 2022-08-02 10:43**MOT test number** 899872974375**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Rear Hydraulic brake cylinder leaking hydraulic fluid (1.1.16 (b) (i))**Advice** All tyres cracked/perished**Fail** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Exhaust system insecure (6.1.2 (a))**MOT #11** 2021-08-14 07:17**MOT test number** 705936648367**Result** ✓ Passed**MOT #10** 2021-08-12 14:47**MOT test number** 440147153694**Result** ✗ Failed**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #9** 2020-09-02 11:37**MOT test number** 906374826609**Result** ✓ Passed**Advice** Offside Rear Outer Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security sill panel (6.2.2 (d) (i))**MOT #8** 2019-09-03 09:02**MOT test number** 102436226015**Result** ✓ Passed

**MOT #7** 2018-09-24 16:18**MOT test number** 319830820680**Result** ✓ Passed**Advice** Central Rear Lower Exhaust mounting defective exhaust hanger bracket corroded but still supporting exhaust (6.1.2 (a))**MOT #6** 2016-10-06 13:37**MOT test number** 772387092133**Result** ✓ Passed**MOT #5** 2015-03-25 16:16**MOT test number** 755874685085**Result** ✓ Passed**MOT #4** 2014-03-20 11:14**MOT test number** 406239274076**Result** ✓ Passed**MOT #3** 2013-03-20 09:55**MOT test number** 427769073072**Result** ✓ Passed**Notice** Back box strap corroded but still secure**MOT #2** 2012-03-29 14:43**MOT test number** 515229182005**Result** ✓ Passed**MOT #1** 2011-03-18 16:16**MOT test number** 115687771452**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
14 May 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	14 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-03-31
Last registration	2023-05-15
Complete history	See info



Registration #1	2008-03-31	12 mi
Registration #2	2011-03-18	13.048 mi
Registration #3	2012-03-29	17.544 mi
Registration #4	2013-03-20	23.540 mi
Registration #5	2014-03-20	29.981 mi
Registration #6	2015-03-25	34.983 mi
Registration #7	2016-10-06	43.527 mi
Registration #8	2018-09-24	53.333 mi
Registration #9	2019-09-03	56.282 mi
Registration #10	2020-05-20	58.377 mi
Registration #11	2020-05-20	58.377 mi
Registration #12	2020-05-20	58.377 mi
Registration #13	2020-05-20	58.377 mi
Registration #14	2020-05-20	58.377 mi
Registration #15	2020-05-20	58.377 mi
Registration #16	2020-05-20	58.377 mi
Registration #17	2020-05-20	58.377 mi
Registration #18	2020-05-20	58.377 mi

More info >



Safety ratings

NCAP rating

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1300 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBAW3003489