



RENAULT

NXIIWUW

report date: 2024-03-29

General information

Make	RENAULT
Model	GRAND SCENIC GRAND DYNAMIQUE TOMTOM VVT
Colour	Grey
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	12.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	151 Nm at 4.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.2 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg





Internet history

Entry 1

Date	2022-01-30
Pictures	2
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #14	2022-10-21 16:50
MOT test number	704046584464
Result	✓ Passed
Next expiry date	2023-10-20
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #13	2021-10-21 08:31
MOT test number	171633559284
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge wearing from inner edge (5.2.3 (e))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12	2021-10-20 13:26
MOT test number	330237320849
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge wearing from inner edge (5.2.3 (e))

MOT #11	2020-09-29 12:47
MOT test number	559247730156
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 205/55/17 (5.2.3 (e))

**MOT #10**

2020-09-28 12:39

MOT test number

192732607083

Result**✗ Failed****Fail**

Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge 205/55/17 (5.2.3 (e))

Fail

Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Fail

Offside Rear Seat belt damaged (7.1.2 (b) (i))

Fail

Offside Front Windscreen wiper does not clear the windscreen effectively aero (3.4 (b) (ii))

Fail

Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #9

2019-10-04 08:53

MOT test number

388577931485

Result**✓ Passed****Advice**

Nearside Play in steering rack inner joint(s)

Advice

Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice

Offside Play in steering rack inner joint(s)

Advice

Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Minor

Offside Windscreen wiper blade defective (3.4 (b) (i))

**MOT #8** 2019-10-03 10:20**MOT test number** 596371786004**Result** ✗ Failed**Fail** Nearside Front Road wheel fixing missing bolt (5.2.1 (a) (i))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Play in steering rack inner joint(s)**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Nearside Play in steering rack inner joint(s)**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #7** 2018-10-08 10:45**MOT test number** 513934749483**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #6** 2018-10-08 10:45**MOT test number** 803927272488**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #5** 2017-10-11 07:44**MOT test number** 141622558594**Result** ✓ Passed

**MOT #4**

2017-10-10 09:09

MOT test number

179704147453

Result**✗ Failed****Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Coolant min**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3**

2016-07-16 11:56

MOT test number

130150955005

Result**✓ Passed****Advice** Offside front tyre worn on outer edge**MOT #2**

2015-07-15 16:14

MOT test number

787426295187

Result**✓ Passed****Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #1**

2014-04-28 13:06

MOT test number

726298514196

Result**✓ Passed****Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside rear tyre**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	0123 456789

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-09
Last registration	2022-10-21
Complete history	See info



Registration #1	2011-03-09	7 mi
Registration #2	2014-04-28	48.135 mi
Registration #3	2015-07-15	64.864 mi
Registration #4	2016-07-16	75.623 mi
Registration #5	2017-10-10	91.409 mi
Registration #6	2017-10-11	91.409 mi
Registration #7	2018-10-08	101.849 mi
Registration #8	2018-10-08	101.849 mi
Registration #9	2019-10-08	101.849 mi
Registration #10	2019-10-08	101.849 mi
Registration #11	2019-10-08	101.849 mi
Registration #12	2019-10-08	101.849 mi
Registration #13	2019-10-08	101.849 mi
Registration #14	2019-10-08	101.849 mi
Registration #15	2019-10-08	101.849 mi
Registration #16	2019-10-08	101.849 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	76%
Pedestrian	42%
Safety systems	99%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1478 mm
Height	1645 mm
Length	4560 mm
Wheel base	2770 mm
Kerb weight	1444 kg
Max. allowed weight	2074 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	D089245