





report date: 2024-03-28

#### General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Black
Year of manufacture	2009
Top speed	125 mph
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	145 BHP
Max. torque	360 Nm at 1.800 rpm
Engine capacity	2.198 сс
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	184 g/km
CO2 label	



CarCheck.co.uk page 1/13



report date: 2024-03-28

#### Internet history

#### Entry 1

Date 2021-10-18

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

	_			
MO	1	hic	to	r\/
				ıv.
				. ,

**Advice** 

MOT expiry date	2024-11-03
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	18
Total items failed	7

MOT #17	2023-11-02 16:23
MOT test number	807421412542
Result	✓ Passed
Next expiry date	2024-11-03

MOT #16	2022-11-04 12:33
MOT test number	330614411474
Result	<b>✓</b> Passed

MOT #15	2022-11-03 13:17
MOT test	number 569378329714
Result	<b>X</b> Failed
<b>Fail</b> C	ffside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Nearside Front Brake lining(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 3/13



report date: 2024-03-28

**MOT #14** 2021-11-04 09:06

**MOT test number** 541945055426

MOT #13 2021-10-26 15:52

**MOT test number** 220900484935

Result × Failed

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #12 2021-02-22 11:22

**MOT test number** 926352911282

**Result** ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

**MOT #11** 2020-02-26 09:46

MOT test number 681138486045

**Result** 
✓ Passed

MOT #10 2019-02-21 14:41

**MOT test number** 442956976987

Result \( \sqrt{Passed} \)

MOT #9 2019-02-19 09:59

**MOT test number** 426354887496

Result X Failed

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #8 2018-03-02 09:43

MOT test number 978665614518

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #7 2018-03-01 10:29

**MOT test number** 236791140342

Result X Failed

Fail Offside Rear coil spring inappropriately repaired (2.4.A.2)

**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #6** 2017-03-02 15:19

**MOT test number** 617546574339

**Result** ✓ Passed

MOT #5 2016-03-08 14:15

**MOT test number** 274672277576

Result \rightarrow Passed

**Advice** Offside Front front brake fluctuating, but not excessively (3.7.B.3)

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened Both side front brake discs inner face scored and lipped. (3.5.1i)

05.11.0

**Advice** Offside Rear coil spring corroded (2.4.C.1b)

**Advice** Engine and under tray cover fitted.

MOT #4 2015-03-05 12:03

MOT test number 758894765043

Result 

Passed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Parking brake lever has little reserve travel (3.1.6b)

**Notice** Plastic sill covers fitted not allowing full inspection of certain underside components

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 5/13



report date: 2024-03-28

2015-03-05 11:41 **MOT** #3 **MOT** test number 438814365086 Result × Failed Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b) Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Advice Parking brake lever has little reserve travel (3.1.6b) Notice Plastic sill covers fitted not allowing full inspection of certain underside components Offside Front Tyre has ply or cords exposed (4.1.D.1b) Fail **Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2	2013-08-29 13:41
MOT test number	857451543280
Result	✓ Passed
MOT #1	2012-08-28 13:49
MOT test number	766041442260
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 May
Days left	1
MOT expiry date	3 November 2024
Full MOT history	See MOT history

#### Tax calculation

CarCheck.co.uk page 7/13



report date: 2024-03-28

#### Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

_	
Owner	hictory
OWITE	HIISLOLY

For how long did the current and previous owner(s) have this JAGUAR? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-01
Last registration	2023-11-02
Complete history	See info



Registration #1	2009-09-01	15 mi
Registration #2	2012-08-28	21.235 mi
Registration #3	2013-08-29	26.536 mi
Registration #4	2015-03-05	33.904 mi
Registration #5	2015-03-05	33.904 mi
Registration #6	2016-03-08	40.898 mi
Registration #7	2017-03-02	46.369 mi
Registration #8	2018-03-01	52.671 mi
Registration #9	2018-03-02	52.672 mi
Registration #10	2019-02-19	53.762 mi
Registration #11		71.777 66
Registration #12		77,777 44
Registration #13		71.777 66
Registration #14		77,777 44
Registration #15		71.777 66
Registration #16		77,777 44
Registration #17		71.777 66
Registration #18		71.777 es
Registration #19		71.777 46

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

### Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	2003 mm
Height	1483 mm
Length	4716 mm
Wheel base	2710 mm
Kerb weight	1605 kg
Max. allowed weight	2120 kg

### Additional information

Fuel tank capacity	61 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	090622085755BG

CarCheck.co.uk page 13/13