





report date: 2024-03-28

General information

Make	BMW
Model	216 216D SPORT GRAN TOURER
Colour	Silver
Year of manufacture	2016
Top speed	119 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.496 cc
Cylinders	3
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.9 mpg
CO2 emission	108 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-09

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-10-25
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	11
Total items failed	9

MOT #9	2023-10-14 17:10
MOT test number	752945354204
Result	✓ Passed
Next expiry date	2024-10-25

MOT #8	2022-10-21 13:04
MOT test number	431635901044
Result	✓ Passed

MOT #7	2021-10-26 14:22
MOT test number	363869042980
Result	✓ Passed

MOT #6	2021-06-14 14:40
MOT test number	941715038172
Result	✓ Passed

MOT #5	2021-06-10 07:37
MOT test number	870076072580

Result × Failed

Fail Offside Front Suspension arm attachment bracket/mounting insecure bolt missing rear bush mountain (5.3.3 (a) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #4 2021-03-30 12:54 **MOT** test number 201313918903 Result × Failed Fail Offside Headlamp aim too low (4.1.2 (a)) **Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Nearside Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i)) **Advice** Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) Fail Offside Obligatory indirect vision device insecure (3.3 (b) (ii)) **Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) **Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT test number

768280202074

Result

Nearside Rear Stop lamp(s) lens defective such that the emitted light is adversely affected (4.3.1 (b)

(ii))

Fail

Offside Rear Stop lamp(s) lens defective such that the emitted light is adversely affected (4.3.1 (b)

MOT #2

MOT test number

702334000151

Result

Minor

Central Obligatory mirror slightly loose (3.3 (b) (i))

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))


Minor

Offside Obligatory mirror slightly damaged (3.3 (b) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-28



CarCheck.co.uk page 5/12



LS16BBV report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	25 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this BMW? How many owners defined the current and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



LS16BBV report date: 2024-03-28

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-05-11
Last registration	2023-10-14
Complete history	See info



Registration #1	2016-05-11	20 mi
Registration #2	2019-06-03	58.451 mi
Registration #3	2019-06-03	58.451 mi
Registration #4	2020-11-20	73.561 mi
Registration #5	2021-03-30	73.811 mi
Registration #6	2021-06-10	73.822 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.70 es
Registration #10		71.777 66
Registration #11		19.707 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditioning
S0295	
S0482	
S0501	
50566	
S0567	
S0569	

Dimensions & weight

Width	1800 mm
Height	1612 mm
Length	4556 mm
Wheel base	2780 mm
Kerb weight	1470 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	51 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	36269553

CarCheck.co.uk page 12/12