



report date: 2024-03-29

General information

Make	FIAT
Model	PANDA ACTIVE ECO
Colour	Blue
Year of manufacture	2010
Top speed	94 mph
0 - 60 mph	15.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	54 BHP
Max. torque	87 Nm at 2.750 rpm
Engine capacity	1.108 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	68.9 mpg
Consumption combined	56.5 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-06-14
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	32
Total items failed	5

MOT #14 2023-06-12 10:54

MOT test number 815871434696

Result ✓ Passed

Next expiry date 2024-06-14

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Exhaust mounting defective exhaust to catalytic convertor clamp very deteriorated (6.1.2 (a))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Coil spring corroded all four (5.3.1 (b) (i))
- Advice** Front Brake hose has slight corrosion to ferrule both (1.1.12 (f) (i))

MOT #13 2022-05-17 14:36

MOT test number 967517874684

Result ✓ Passed

- Advice** Front Exhaust mounting defective (6.1.2 (a))
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Coil spring corroded all four (5.3.1 (b) (i))
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Rear exhaust silencer deteriorated

**MOT #12**

2022-05-17 10:17

MOT test number

533059812200

Result

✗ Failed

Advice Rear exhaust silencer deteriorated**Fail** Offside Front Headlamp aim too high (4.1.2 (a))**Advice** Coil spring corroded all four (5.3.1 (b) (i))**Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Front Exhaust mounting defective (6.1.2 (a))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #11**

2021-06-15 11:11

MOT test number

392271034210

Result

✓ Passed

Advice Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #10**

2020-09-26 10:46

MOT test number

872927989584

Result

✓ Passed

**MOT #9** 2019-10-23 08:13**MOT test number** 550379070006**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing Outer side wall. (5.2.3 (d) (ii))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #8** 2018-10-23 12:25**MOT test number** 373720288576**Result** ✓ Passed**MOT #7** 2017-10-25 13:26**MOT test number** 325707417107**Result** ✓ Passed**MOT #6** 2016-10-18 12:44**MOT test number** 370761002378**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-10-18 11:06**MOT test number** 472921070912**Result** ✗ Failed**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2015-10-20 11:04**MOT test number** 397210682761**Result** ✓ Passed**Advice** Rear shock absorber top bush splitting**Advice** Exhaust rear back box clamp heavily corroded**MOT #3** 2014-11-11 16:20**MOT test number** 356565414322**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Nail in offside rear tyre**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2014-11-11 15:00**MOT test number** 146605114381**Result** ✗ Failed**Notice** Nail in offside rear tyre**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2013-11-27 15:06**MOT test number** 167091033303**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
14 June 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	14 June 2024
Full MOT history	See MOT history

Tax calculation


Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2019-06-29
Current registration	 XXXXX
Plate since	2019-06-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-12-13
Last registration	2023-06-12
Complete history	See info



Registration #1	2010-12-13	7 mi
Registration #2	2013-11-27	11.527 mi
Registration #3	2014-11-11	13.990 mi
Registration #4	2014-11-11	13.990 mi
Registration #5	2015-10-20	16.128 mi
Registration #6	2016-10-18	17.595 mi
Registration #7	2016-10-18	17.595 mi
Registration #8	2017-10-25	18.969 mi
Registration #9	2019-05-20	20.277 mi
Registration #10	2019-05-20	20.277 mi
Registration #11	2019-05-20	20.277 mi
Registration #12	2019-05-20	20.277 mi
Registration #13	2019-05-20	20.277 mi
Registration #14	2019-05-20	20.277 mi
Registration #15	2019-05-20	20.277 mi
Registration #16	2019-05-20	20.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1578 mm
Height	1540 mm
Length	3538 mm
Wheel base	2299 mm
Kerb weight	840 kg
Max. allowed weight	1255 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

Number of axles	2
Engine number	5718881