



report date: 2024-03-29

General information

Make	KIA
Model	CEED CRDI 2
Colour	Red
Year of manufacture	2011
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	255 Nm at 2.750 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	118 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-06-19
Pictures	11
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-08
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	39
Total items failed	6

MOT #13 2023-05-30 14:52

MOT test number 599521492868

Result ✓ Passed

Next expiry date 2024-06-08

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #12**

2022-06-08 12:04

**MOT test number**

325977507892

**Result**

✓ Passed

**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Front Outer Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear Brake pad(s) wearing thin Both rear wearing thin (1.1.13 (a) (ii))**MOT #11**

2022-06-08 08:22

**MOT test number**

794419609649

**Result**

✗ Failed

**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear Brake pad(s) wearing thin Both rear wearing thin (1.1.13 (a) (ii))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Outer Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MOT #10**

2021-06-09 15:13

**MOT test number**

641321626221

**Result**

✓ Passed

**MOT #9**

2021-06-09 15:13

**MOT test number**

778623021204

**Result**

✗ Failed

**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #8** 2020-10-23 14:35**MOT test number** 541428759874**Result** ✓ Passed**MOT #7** 2019-10-09 15:22**MOT test number** 575894188043**Result** ✓ Passed**MOT #6** 2018-10-29 11:43**MOT test number** 688440957485**Result** ✓ Passed**MOT #5** 2017-10-27 14:16**MOT test number** 867074738035**Result** ✓ Passed

- Advice** Coolant bottle empty
- Advice** Engine oil leaks from turbo pipe.
- Advice** Rear tyres perished.
- Advice** Offside Rear Nail in tyre
- Advice** N/S/R lamp damaged but not showing white light to rear.
- Advice** N/S inner CV boot slight leak from clip.

**MOT #4**

2017-10-25 14:45

**MOT test number**

495649793611

**Result****✗ Failed**

**Fail** Offside Front Lower Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

**Advice** N/S inner CV boot slight leak from clip.

**Advice** Offside Rear Nail in tyre

**Advice** Coolant bottle empty

**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice** Engine oil leaks from turbo pipe.

**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**Advice** Rear tyres perished.

**Advice** N/S/R lamp damaged but not showing white light to rear.

**MOT #3**

2016-10-08 11:40

**MOT test number**

266968801545

**Result****✓ Passed**

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Emissions too low to detect

**Advice** Nearside Rear Direction indicator damaged, but still visible from a reasonable distance (1.4.A.2e)



MOT #2	2015-10-27 09:27
MOT test number	771858572549
Result	✓ Passed

MOT #1	2014-10-28 12:43
MOT test number	508091804302
Result	✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
8 June 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	32
<b>MOT expiry date</b>	8 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>LC61JJY</b>
Plate since	2024-03-29
Current registration	<b>LC61JJY</b>
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-10-31
Last registration	2023-05-30
Complete history	<a href="#">See info</a>



Registration #1	2011-10-31	23 mi
Registration #2	2014-10-28	17.764 mi
Registration #3	2015-10-27	35.602 mi
Registration #4	2016-10-08	52.714 mi
Registration #5	2017-10-25	72.615 mi
Registration #6	2017-10-27	72.761 mi
Registration #7	2018-10-29	87.842 mi
Registration #8	2019-10-09	97.832 mi
Registration #9	2020-05-20	101.277 mi
Registration #10	2020-05-20	101.277 mi
Registration #11	2020-05-20	101.277 mi
Registration #12	2020-05-20	101.277 mi
Registration #13	2020-05-20	101.277 mi
Registration #14	2020-05-20	101.277 mi
Registration #15	2020-05-20	101.277 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1790 mm
Height	1480 mm
Length	4260 mm
Wheel base	2650 mm
Kerb weight	1468 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FBBZ350390