





General information

Make	HYUNDAI
Model	KONA PREMIUM SE
Colour	Grey
Year of manufacture	2019
Top speed	104 mph
0 - 60 mph	7.6 seconds
Gearbox	1 speed automatic

Engine & fuel consumption

Power	201 BHP
Max. torque	395 Nm
Fuel type	Electricity
Consumption combined	1.0 mpg







Internet history


Entry 1

Date Pictures 2021-06-06

30

Listing price

View report



source: yesauto.com



MOT history

MOT expiry date	2024-09-19
MOT pass rate	67 %
MOT passed	2
Failed MOT tests	1
Total advice items	11
Total items failed	1

МОТ #3	2023-09-19 16:41	
MOT test number	437542896637	
Result	🗸 Passed	
Next expiry date	2024-09-19	
Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords smooth on inner edge (5.2.3 (d) (i))		
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt		
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cord	ds (5.2.3 (d) (i))	
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or correct	ds (5.2.3 (d) (i))	

МОТ #2	2023-09-19 15:59	
MOT test number	839393744363	
Result	× Failed	
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cord	ds (5.2.3 (d) (i))	
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))		
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt		
Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))		
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cor	ds (5.2.3 (d) (i))	
Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))	smooth on inner edge	






MOT #1		2022-09-20 12:26
MOT test	number	817297705442
Result		✓ Passed
Advice Child seat fitted to near side rear seat, not allowing full inspection of an adult seat belt.		
Advice	Both rear tyres wearing on inner edge.	



Tax & MOT check







Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Date	AF I
Category	ante.
Туре	

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Plate since Carrent registration	







Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow



RV690BC report date: 2024-03-29

Mileage check

In miles
5
2019-09-20
2023-09-19
<u>See info</u>



Registration #1	2019-09-20	29 mi
Registration #2		11.777 est
Registration #3	2022-09-20	22.322 mi
Registration #4		11.777 est
Registration #5		10.200 mi

More info >






Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	87%
Children	85%
Pedestrian	62%
Safety systems	60%
Overall rating	76%
Video	see crash video



Dimensions & weight	
Width	2070 mm
Height	1570 mm
Length	4180 mm
Wheel base	2600 mm
Max. allowed weight	2170 kg
Additional information	

Fuel delivery	Not Applicable	
Number of doors	5	
Number of seats	5	
Number of axles	2	
Engine number Carcheck.co.uk	EM16JCD514B	page 11/11