




report date: 2024-11-06

General information

Make	MINI
Model	MINI COOPER S
Colour	Blue
Year of manufacture	2003
Top speed	135 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	210 Nm at 4.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	33.6 mpg
CO2 emission	202 g/km
CO2 label	K





MOT history

MOT expiry date	2024-03-09
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	34
Total items failed	22

MOT #23 2024-03-11 12:58

MOT test number 668354316895

Result ✗ Failed

- Fail** Rear Exhaust has a major leak of exhaust gases back box (6.1.2 (a))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Rear power cable dragging on floor
- Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength chassis (5.3.6 (a) (i))
- Fail** Offside Front Driver's seat insecure (6.2.5 (a) (ii))
- Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength chassis (5.3.6 (a) (i))
- Advice** Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Rear Service brake excessively fluctuating (1.2.1 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength floor (5.3.6 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake hose has slight corrosion to ferrule both (1.1.12 (f) (i))



MOT #22	2023-03-10 13:06
MOT test number	513282819456
Result	✓ Passed

MOT #21	2022-03-10 16:36
MOT test number	586451499256
Result	✓ Passed
Advice	Front Brake pipe corroded, covered in grease or other material both front (1.1.11 (c))
Advice	Various items corroded under vehicle
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Tyre worn close to legal limit/worn on edge all 4 tyres close to legal limit (5.2.3 (e))

MOT #20	2018-07-18 11:14
MOT test number	395824514762
Result	✓ Passed

MOT #19	2018-07-17 14:23
MOT test number	158671128339
Result	✗ Failed
Fail	Brake pad(s) wear indicator illuminated (1.1.13 (a) (i))

MOT #18	2017-07-31 07:53
MOT test number	116138329880
Result	✓ Passed
Advice	Brake pad warning light on.



MOT #17 2017-07-24 10:44

MOT test number 804419131182

Result ✗ Failed

Fail Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush. (2.4.G.2)

Advice Nearside Front tyre worn on inner edge.

Advice Brake pad warning light on.

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush. (2.4.G.2)

Fail Bonnet cannot be secured in the closed position (8.4.1)

Advice Tyre pressure monitoring light on.

MOT #16 2016-07-29 11:18

MOT test number 141849996188

Result ✓ Passed

Advice Knocking on rear

Advice Oil leak

Advice Amber brake warning lamp on dash at time of test

MOT #15 2016-07-27 09:13

MOT test number 361806990598

Result ✗ Failed

Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

Advice Knocking on rear

Advice Oil leak

Advice Amber brake warning lamp on dash at time of test



MOT #14 2015-07-28 15:24

MOT test number 735179905273

Result ✔ Passed

MOT #13 2015-07-22 12:41

MOT test number 306083405450

Result ✘ Failed

Fail Nearside Inner Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Offside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #12 2014-07-23 12:10

MOT test number 906544704252

Result ✔ Passed

MOT #11 2014-07-21 12:44

MOT test number 905672404225

Result ✘ Failed

Fail Offside Rear Brake pipe excessively corroded (3.6.B.2c)

Fail Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

Notice Oil leak

MOT #10 2013-07-30 13:14

MOT test number 359581513420

Result ✔ Passed

Advice Front Brake pipe slightly corroded (3.6.B.2c)

Notice Rear exhaust bracket broken



MOT #9 2012-07-31 16:53

MOT test number 157923012226

Result ✔ Passed

MOT #8 2011-11-01 12:37

MOT test number 577325701348

Result ✔ Passed

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #7 2010-11-03 14:59

MOT test number 743717000317

Result ✔ Passed

Notice Oil leak

Advice Exhaust has part of the system slightly deteriorated (7.1.1a)

MOT #6 2010-11-01 16:47

MOT test number 423965600403

Result ✘ Failed

Advice Exhaust has part of the system slightly deteriorated (7.1.1a)

Fail Offside Front position lamp(s) not working (1.1.A.3b)

Fail Offside Headlamp aim too low (1.8)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Brake pipe slightly corroded (3.6.B.2c)

Fail Offside Rear Tyre has ply or cords exposed (4.1.D.1b)

Notice Oil leak

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #5 2010-01-11 15:39

MOT test number 124601810009

Result ✓ Passed

MOT #4 2009-01-12 15:17

MOT test number 294812119034

Result ✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3 2009-01-12 12:28

MOT test number 791322619084

Result ✗ Failed

Fail Nearside Rear brake disc excessively pitted (3.5.1h)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Offside Rear brake disc excessively pitted (3.5.1h)

MOT #2 2008-02-04 15:28

MOT test number 864125838067

Result ✓ Passed

MOT #1 2007-02-20 14:24

MOT test number 302481757036

Result ✓ Passed




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	YK53KXX
Plate since	2019-09-29
Current registration	YK53KXX
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-09-05
Last registration	2024-03-11
Complete history	See info



Registration #1	2003-09-05	20 mi
Registration #2	2007-02-20	35.967 mi
Registration #3	2008-02-04	43.591 mi
Registration #4	2009-01-12	50.455 mi
Registration #5	2009-01-12	50.455 mi
Registration #6	2010-01-11	59.462 mi
Registration #7	2010-11-01	65.917 mi
Registration #8	2010-11-03	65.917 mi
Registration #9	2011-11-01	75.042 mi
Registration #10	2012-07-31	81.279 mi
Registration #11	2013-07-30	89.283 mi
Registration #12	2014-07-21	99.904 mi
Registration #13	2015-05-20	101.277 mi
Registration #14	2015-05-20	101.277 mi
Registration #15	2015-05-20	101.277 mi
Registration #16	2015-05-20	101.277 mi
Registration #17	2015-05-20	101.277 mi
Registration #18	2015-05-20	101.277 mi
Registration #19	2015-05-20	101.277 mi
Registration #20	2015-05-20	101.277 mi
Registration #21	2015-05-20	101.277 mi
Registration #22	2015-05-20	101.277 mi
Registration #23	2015-05-20	101.277 mi
Registration #24	2015-05-20	101.277 mi

[More info >](#)



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1925 mm
Height	1416 mm
Length	3655 mm
Wheel base	2467 mm
Kerb weight	1140 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	D252R132