



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	MR2 ROADSTER
Colour	Silver
Year of manufacture	2003
Top speed	130 mph
0 - 60 mph	7.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	47.9 mpg
Consumption combined	38.2 mpg
CO2 emission	178 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-06-11
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-19
MOT pass rate	63 %
MOT passed	17
Failed MOT tests	10
Total advice items	52
Total items failed	17

MOT #27 2023-06-08 09:15

MOT test number 271881727414

Result ✓ Passed

Next expiry date 2024-06-19

Advice Nearside Rear Requirements only just met. Appears braking system requires adjustment or repair

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #26 2023-06-08 09:15

MOT test number 233270622306

Result ✗ Failed

Pass with rectification Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Nearside Rear Requirements only just met. Appears braking system requires adjustment or repair

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #25 2022-06-20 08:21

MOT test number 506128147879

Result ✓ Passed

Advice Offside Rear Nail in tyre

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 3mm tread 205/50/15 (5.2.3 (e))

**MOT #24** 2022-06-07 09:12**MOT test number** 686117853793**Result** ✗ Failed**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm tread 205/50/15 (5.2.3 (e))**Advice** Offside Rear Nail in tyre**DANGEROUS** Nearside Front Outer Tyre has a lump, caused by separation or partial failure of its structure 185/55/15 (5.2.3 (d) (ii))**MAJOR** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**MOT #23** 2021-06-08 15:12**MOT test number** 666126948484**Result** ✓ Passed**MOT #22** 2021-06-01 14:51**MOT test number** 245048814435**Result** ✗ Failed**MAJOR** Offside Front Seat belt buckle not functioning as intended (7.1.2 (d))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MAJOR** Nearside Front Seat belt buckle not functioning as intended (7.1.2 (d))**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**MOT #21** 2019-05-24 16:56**MOT test number** 423909869255**Result** ✓ Passed

**MOT #20** 2018-07-17 13:28**MOT test number** 680483192001**Result** ✓ Passed**Advice** Front Power steering pipe/hose slightly corroded (2.1.5 (g) (i))**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front brake hose bracket insecure**MOT #19** 2018-07-17 13:28**MOT test number** 497873928773**Result** ✗ Failed**Pass with rectification** Front Registration plate incorrect (0.1 (c))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Nearside Front brake hose bracket insecure**Advice** Front Power steering pipe/hose slightly corroded (2.1.5 (g) (i))**Pass with rectification** Rear Registration plate incorrect (0.1 (c))**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**MOT #18** 2017-06-14 08:34**MOT test number** 959910704152**Result** ✓ Passed

**MOT #17** 2016-08-02 09:09**MOT test number** 427194334719**Result** ✓ Passed

- Advice** Nearside Front tyre wall slightly perished
- Advice** Slightly oil leak
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #16 2016-07-12 10:00**MOT test number** 156906844786**Result** ✗ Failed

- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Advice** Chips to windscreen
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)
- Advice** Nearside handbrake low effort
- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #15 2015-05-22 15:23**MOT test number** 219022245429**Result** ✓ Passed

- Notice** N/s/r tyre perished
- Advice** Parking brake lever has little reserve travel (3.1.6b)



MOT #14	2015-05-16 11:26
MOT test number	585456635164
Result	✗ Failed
Notice	N/s/r tyre perished
Fail	Parking brake: efficiency below requirements (3.7.B.7)

MOT #13	2014-04-14 16:34
MOT test number	467624504130
Result	✓ Passed
Notice	Offside front tyre perishing
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Front coil spring corroded (2.4.C.1b)
Advice	Rear Sub-frame corroded but not seriously weakened (2.4.G.1)

MOT #12	2014-04-10 17:09
MOT test number	219980704459
Result	✗ Failed
Advice	Front coil spring corroded (2.4.C.1b)
Fail	Parking brake: efficiency below requirements (3.7.B.7)
Advice	Rear Sub-frame corroded but not seriously weakened (2.4.G.1)
Notice	Offside front tyre perishing
Fail	Offside rear parking brake recording little or no effort (3.7.B.6a)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #11** 2013-03-28 10:10**MOT test number** 557517383071**Result** ✓ Passed**Advice** Front Anti-roll bar corroded but not seriously weakened (2.4.G.1)**Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Offside Front coil spring corroded (2.4.C.1b)**Advice** Nearside Front coil spring corroded (2.4.C.1b)**MOT #10** 2012-07-06 15:31**MOT test number** 989278082144**Result** ✓ Passed**MOT #9** 2011-07-08 16:34**MOT test number** 489179581163**Result** ✓ Passed**MOT #8** 2011-07-04 11:02**MOT test number** 485845881182**Result** ✗ Failed**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**MOT #7** 2010-04-08 09:12**MOT test number** 563188390045**Result** ✗ Failed**Advice** Front brake disc slightly pitted (3.5.1h)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #6** 2010-04-08 09:12**MOT test number** 290048090037**Result** ✓ Passed**Advice** Front brake disc slightly pitted (3.5.1h)**MOT #5** 2009-01-22 16:46**MOT test number** 553232729002**Result** ✓ Passed**Notice** Offside front and offside rear tyres,tread worn on both edges.**Notice** Offside windscreen washer jet aims a bit high.**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2008-04-07 15:51**MOT test number** 714028598039**Result** ✓ Passed**Advice** Front brake disc slightly pitted (3.5.1h)**MOT #3** 2007-04-11 11:00**MOT test number** 473171707117**Result** ✓ Passed**MOT #2** 2006-03-30 17:13**MOT test number** 162019886416**Result** ✓ Passed



MOT #1	2006-03-14 15:36
MOT test number	584973376040
Result	✗ Failed
Fail	Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)
Fail	Offside Front Windscreen wiper blade deteriorated (8.2.2)
Fail	Nearside Front Windscreen wiper blade deteriorated (8.2.2)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
19 June 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	19 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2003-04-09
Last registration	2023-06-08
Complete history	See info



Registration #1	2003-04-09	6 mi
Registration #2	2006-03-14	27.606 mi
Registration #3	2006-03-30	27.865 mi
Registration #4	2007-04-11	37.414 mi
Registration #5	2008-04-07	48.090 mi
Registration #6	2009-01-22	54.522 mi
Registration #7	2010-04-08	61.631 mi
Registration #8	2011-07-04	69.000 mi
Registration #9	2011-07-08	69.000 mi
Registration #10	2012-07-06	74.182 mi
Registration #11	2013-03-28	74.963 mi
Registration #12	2014-04-10	83.535 mi
Registration #13	2014-04-14	83.616 mi
Registration #14	2015-05-16	95.881 mi
Registration #15	2015-05-16	95.881 mi
Registration #16	2015-05-16	95.881 mi
Registration #17	2015-05-16	95.881 mi
Registration #18	2015-05-16	95.881 mi
Registration #19	2015-05-16	95.881 mi
Registration #20	2015-05-16	95.881 mi
Registration #21	2015-05-16	95.881 mi
Registration #22	2015-05-16	95.881 mi
Registration #23	2015-05-16	95.881 mi
Registration #24	2015-05-16	95.881 mi
Registration #25	2015-05-16	95.881 mi
Registration #26	2015-05-16	95.881 mi

Registration #27	2025-25-25	25,252,452
Registration #28	2025-25-25	25,252,452

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1695 mm
Height	1240 mm
Length	3885 mm
Wheel base	2450 mm
Kerb weight	960 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	1ZZ1399992