



report date: 2024-03-29

General information

Make	FIAT
Model	DOBLO 16V MULTIJET II
Colour	White
Year of manufacture	2017
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history


Entry 1

Date	2022-05-15
Pictures	1
Listing price	<a href="#">View report</a>

AA

This dealer has signed up to our **Dealer Promise.**

- Free history check
- 6 months (minimum) MOT
- Free 12 months Breakdown cover

[aacars.com](#)

source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2025-04-25
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	17
Total items failed	3

MOT #7	2024-04-13 14:00
MOT test number	782599264543
Result	✓ Passed
Next expiry date	2025-04-25
Advice	Nearside Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Central Rear Lower Gearbox mounting defective Badly worn/split

MOT #6	2024-04-13 08:38
MOT test number	660058798551
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge Worn down to 2mm and badly worn on the inner edge to the secondary rubber layer 185 65 15 88H Budget (5.2.3 (e))
Advice	Nearside Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Central Rear Lower Gearbox mounting defective Badly worn/split
Minor	Offside Rear Tyre obviously under inflated Also has screw in the central tread block (5.2.3 (I))
Advice	Central Little reserve travel left on Park/Handbrake lever
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Worn down to 2mm and badly worn on the inner edge to the secondary rubber layer 185 65 15 88H Budget (5.2.3 (e))
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively Split (3.4 (b) (ii))

**MOT #5** 2023-04-26 13:47**MOT test number** 658665825263**Result** ✓ Passed**Advice** Nearside Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #4** 2023-04-26 10:50**MOT test number** 791823979423**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #3** 2022-02-02 11:08**MOT test number** 318803705465**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #2** 2021-01-11 14:06**MOT test number** 971762032106**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Nail in tyre**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Rear tyres perished



MOT #1	2020-01-08 11:16
MOT test number	931097116492
Result	✓ Passed
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
25 April 2025

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	366
<b>MOT expiry date</b>	25 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-01-12
Last registration	2024-04-13
Complete history	<a href="#">See info</a>



Registration #1	2017-01-12	26 mi
Registration #2	2020-01-08	29.376 mi
Registration #3	2021-01-11	38.143 mi
Registration #4	2022-02-02	46.886 mi
Registration #5	2023-03-20	55.277 mi
Registration #6	2023-03-20	55.277 mi
Registration #7	2023-03-20	55.277 mi
Registration #8	2023-03-20	55.277 mi
Registration #9	2024-04-13	55.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	6374782