



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY LIFE TDI
Colour	Blue
Year of manufacture	2009
Top speed	103 mph
Gearbox	5 speed Semi Auto

Engine & fuel consumption

Power	104 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.8 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-07-07
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-09
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	20
Total items failed	0

MOT #14	2023-11-01 12:35
MOT test number	212670158226
Result	✓ Passed
Next expiry date	2024-11-09
Advice	Offside Rear door cannot be open from inside or outside / poss due to conversion
Advice	Front Exhaust mounting defective (6.1.2 (a))
Advice	Nearside Rear Suspension component pin or bush slightly worn (5.3.4 (a) (i))

MOT #13	2022-11-10 16:49
MOT test number	934289967461
Result	✓ Passed
Advice	Offside Rear door cannot be opened from inside or outside / poss due to conversion
Advice	Front Exhaust mounting defective (6.1.2 (a))

**MOT #12** 2022-06-14 16:02**MOT test number** 178504168170**Result** ✗ Failed**Advice** Front Exhaust mounting defective (6.1.2 (a))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Rear Electrical wiring insecure (4.11 (a) (i))**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MAJOR** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear door cannot be opened from inside or outside / poss due to conversion**MOT #11** 2021-06-29 13:07**MOT test number** 292918138393**Result** ✓ Passed**MOT #10** 2020-02-04 15:13**MOT test number** 522865855811**Result** ✓ Passed**Advice** Offside Rear door does not function as a door due to possible disabled modification**MOT #9** 2020-02-04 11:54**MOT test number** 589237764867**Result** ✗ Failed**MAJOR** Offside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))**DANGEROUS** Driver's seat insecure (6.2.5 (a) (ii))**MAJOR** Exhaust emissions exceed manufacturer's specified limit plate limit 1.30 (8.2.2.2 (a))

**MOT #8** 2019-04-25 13:35**MOT test number** 708852388777**Result** ✓ Passed**MOT #7** 2018-03-22 11:51**MOT test number** 345197114010**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2017-03-20 17:46**MOT test number** 749601389085**Result** ✓ Passed**MOT #5** 2016-11-28 14:41**MOT test number** 713679183173**Result** ✓ Passed**Advice** Offside Front Tyre bald around inner edge**MOT #4** 2015-12-11 13:39**MOT test number** 919754503063**Result** ✓ Passed**MOT #3** 2014-11-12 14:40**MOT test number** 755356714324**Result** ✓ Passed**Notice** O/s slinding door can not be opened



MOT #2	2013-11-13 15:18
MOT test number	678487513399
Result	✓ Passed

MOT #1	2012-11-22 14:16
MOT test number	545417922399
Result	✓ Passed

**Notice** Offside windscreen wiper deteriorated



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
9 November 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	185
<b>MOT expiry date</b>	9 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>BN59EFK</b>
Plate since	2024-03-29
Current registration	 <b>BN59EFK</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-12-18
Last registration	2023-11-01
Complete history	<a href="#">See info</a>



Registration #1	2009-12-18	8 mi
Registration #2	2012-11-22	6.806 mi
Registration #3	2013-11-13	8.576 mi
Registration #4	2014-11-12	10.241 mi
Registration #5	2015-12-11	11.803 mi
Registration #6	2016-11-28	12.781 mi
Registration #7	2017-03-20	13.182 mi
Registration #8	2018-03-22	13.803 mi
Registration #9	2019-03-22	14.424 mi
Registration #10	2020-03-22	15.045 mi
Registration #11	2021-03-22	15.666 mi
Registration #12	2022-03-22	16.287 mi
Registration #13	2023-03-22	16.908 mi
Registration #14	2024-03-22	17.529 mi
Registration #15	2025-03-22	18.150 mi
Registration #16	2026-03-22	18.771 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2062 mm
Height	1833 mm
Length	4405 mm
Max. allowed weight	2280 kg

Additional information

Number of seats	5
Number of axles	2
Engine number	BLS0A73029