



report date: 2024-03-29

General information

Make	MINI
Model	ONE
Colour	Red
Year of manufacture	2012
Top speed	116 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-05-21
Pictures	26
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-15
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	25
Total items failed	3

MOT #12 2023-08-04 12:29

MOT test number 266083326743

Result ✓ Passed

Next expiry date 2024-08-15

- Advice** Nearside Rear Lower Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Tyre slightly damaged/cracking or perishing both tyres cracking. (5.2.3 (d) (ii))
- Advice** Subframes have corrosion.
- Minor** Front Electrical wiring insecure lambda sensor wires insecure. (4.11 (a) (i))
- Advice** Central exhaust sleeve corroded and fouling body.

MOT #11 2023-08-02 10:00

MOT test number 602592777397

Result ✗ Failed

- Minor** Front Electrical wiring insecure lambda sensor wires insecure. (4.11 (a) (i))
- Advice** Subframes have corrosion.
- Advice** Nearside Rear Lower Coil spring corroded (5.3.1 (b) (i))
- Advice** Central exhaust sleeve corroded and fouling body.
- Advice** Rear Tyre slightly damaged/cracking or perishing both tyres cracking. (5.2.3 (d) (ii))
- Fail** Offside Front Lower Coil spring fractured or broken replace. (5.3.1 (b) (i))

**MOT #10**

2022-08-16 07:00

MOT test number

737198940637

Result

✓ Passed

Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #9

2021-07-05 13:11

MOT test number

647089968159

Result

✓ Passed

Advice

Coolant below minimum

Advice

Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords 175/65/15 (5.2.3 (d) (i))

Advice

Rear seats not in use

Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice

Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #8

2020-10-27 10:47

MOT test number

292937943101

Result

✓ Passed

Minor

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #7

2019-11-05 17:03

MOT test number

485319465089

Result

✓ Passed

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement main rear bush (5.3.4 (a) (i))

Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #6** 2019-11-05 14:13**MOT test number** 636384831514**Result** ✗ Failed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement main rear bush (5.3.4 (a) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #5** 2018-11-07 12:43**MOT test number** 446201036291**Result** ✓ Passed**Advice** Nearside Rear brake binding slightly**MOT #4** 2017-11-16 09:31**MOT test number** 436565554504**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear tyre worn outer edge**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2016-11-21 10:46**MOT test number** 241497020258**Result** ✓ Passed**MOT #2** 2016-11-21 10:46**MOT test number** 303716933360**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #1	2015-10-15 09:42
MOT test number	975072427793
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
15 August 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	15 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-09-27
Last registration	2023-08-04
Complete history	See info



Registration #1	2012-09-27	20 mi
Registration #2	2015-10-15	26.574 mi
Registration #3	2016-11-21	32.068 mi
Registration #4	2016-11-21	32.068 mi
Registration #5	2017-11-16	40.589 mi
Registration #6	2018-11-07	47.042 mi
Registration #7	2019-11-05	52.636 mi
Registration #8	2020-05-20	55.277 mi
Registration #9	2020-05-20	55.277 mi
Registration #10	2020-05-20	55.277 mi
Registration #11	2020-05-20	55.277 mi
Registration #12	2020-05-20	55.277 mi
Registration #13	2020-05-20	55.277 mi
Registration #14	2023-08-04	55.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	A024J283