



report date: 2024-03-29

General information

Make	MINI
Model	PACEMAN COOPER SD
Colour	Red
Year of manufacture	2016
Top speed	123 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	61.4 mpg
CO2 emission	124 g/km
CO2 label	D





Internet history

Entry 3

Date	2022-11-21
Pictures	8
Listing price	View report



source: autotrader.co.uk

Entry 2


Date	2022-04-12
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-29
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-30
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	2
Total items failed	10

MOT #10	2023-11-28 14:57
MOT test number	685771738167
Result	✓ Passed
Next expiry date	2024-11-30

MOT #9	2022-12-01 11:51
MOT test number	772186521034
Result	✓ Passed

MOT #8	2022-05-23 10:24
MOT test number	623735671358
Result	✓ Passed

MOT #7	2021-11-02 16:29
MOT test number	530171031515
Result	✓ Passed

**MOT #6** 2021-10-22 13:27**MOT test number** 187819900113**Result** ✗ Failed

- Fail** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Offside Front Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Undertray likely to become detached (6.2.1 (a) (ii))
- Fail** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #5 2021-03-31 13:21**MOT test number** 849994956931**Result** ✓ Passed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #4 2021-03-31 13:21**MOT test number** 725477925745**Result** ✗ Failed

- Pass with rectification** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #3 2020-03-02 17:34**MOT test number** 758678232992**Result** ✓ Passed



MOT #2	2019-05-01 12:24
MOT test number	375587220832
Result	✓ Passed

MOT #1	2019-05-01 11:37
MOT test number	831145700278
Result	✗ Failed

Fail

Horn not working (7.7 (a) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
30 November 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	30 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2016-05-10
Last registration	2023-11-28
Complete history	See info



Registration #1	2016-05-10	15 mi
Registration #2	2019-05-01	23.026 mi
Registration #3	2019-05-01	23.026 mi
Registration #4	2020-03-02	32.102 mi
Registration #5	2021-03-31	38.826 mi
Registration #6	2021-03-31	38.826 mi
Registration #7	2022-03-31	45.550 mi
Registration #8	2022-03-31	45.550 mi
Registration #9	2022-03-31	45.550 mi
Registration #10	2022-03-31	45.550 mi
Registration #11	2022-03-31	45.550 mi
Registration #12	2022-03-31	45.550 mi
Registration #13	2022-03-31	45.550 mi
Registration #14	2023-11-28	45.550 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1320 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	72829525
---------------	----------