



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Red
Year of manufacture	2005
Top speed	111 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-08-05
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-27
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	37
Total items failed	3

MOT #17	2023-06-23 09:02
MOT test number	415757633995
Result	✓ Passed
Next expiry date	2024-06-27
Advice	Front Macpherson strut pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))

MOT #16	2022-06-28 14:41
MOT test number	379427271484
Result	✓ Passed

**MOT #15**

2021-06-22 15:29

**MOT test number**

292147823859

**Result**

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Brake cable damaged but not to excess Both (1.1.15 (a))
- Minor** Headlamp lens slightly defective Both (4.1.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Petrol flap difficult to open
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened All (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14**

2019-04-06 09:45

**MOT test number**

301543258676

**Result**

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))

**MOT #13**

2018-04-18 16:30

**MOT test number**

145899384067

**Result**

✓ Passed

**Advice**

Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

**Advice**

Nearside Rear tyre tread worn on edges (3mm in testable area)

**Advice**

Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

**Advice**

Nearside wiper blade deteriorating

**Advice**

Offside Rear tyre tread worn on edges (3mm in testable area)

**MOT #12**

2018-04-18 16:30

**MOT test number**

538598675570

**Result**

✗ Failed

**Advice**

Nearside wiper blade deteriorating

**Advice**

Offside Rear tyre tread worn on edges (3mm in testable area)

**Advice**

Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

**Advice**

Nearside Rear tyre tread worn on edges (3mm in testable area)

**Pass with rectification**

Nearside Headlamp not working on dipped beam (1.7.5a)

**Advice**

Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

**MOT #11**

2017-04-07 10:20

**MOT test number**

920773535539

**Result**

✓ Passed

**Advice**

Central exhaust mounting broken

**Advice**

Offside Rear tyre perishing

**Advice**

Offside Rear tyre getting low on outer edge

**MOT #10** 2016-04-21 16:28**MOT test number** 327554927095**Result** ✓ Passed**Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Centre exhaust mounting separated**MOT #9** 2015-04-16 14:51**MOT test number** 238786305475**Result** ✓ Passed**Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2014-03-10 12:30**MOT test number** 108919864435**Result** ✓ Passed**MOT #7** 2013-03-25 16:14**MOT test number** 668934083030**Result** ✓ Passed

**MOT #6** 2012-03-15 16:10**MOT test number** 145065872433**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Tyres cracking with age**MOT #5** 2011-03-31 11:34**MOT test number** 346440091036**Result** ✓ Passed**MOT #4** 2010-04-06 15:03**MOT test number** 842736090001**Result** ✓ Passed**MOT #3** 2009-04-08 11:29**MOT test number** 172458399079**Result** ✓ Passed**MOT #2** 2008-04-10 16:54**MOT test number** 704471508145**Result** ✓ Passed



MOT #1	2008-04-10 15:37
MOT test number	624081208180
Result	✗ Failed
Fail	Rear registration plate character(s) incorrectly spaced (6.3.4a)
Fail	Front registration plate character(s) incorrectly spaced (6.3.4a)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
27 June 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	27 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>BN05VVH</b>
Plate since	2020-03-29
Current registration	 <b>BN05VVH</b>
Plate since	2020-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-03-22
Last registration	2023-06-23
Complete history	<a href="#">See info</a>



Registration #1	2005-03-22	11 mi
Registration #2	2008-04-10	12.307 mi
Registration #3	2008-04-10	12.307 mi
Registration #4	2009-04-08	17.849 mi
Registration #5	2010-04-06	23.344 mi
Registration #6	2011-03-31	27.699 mi
Registration #7	2012-03-15	30.758 mi
Registration #8	2013-03-25	34.445 mi
Registration #9	2014-03-10	37.820 mi
Registration #10	2015-04-16	42.585 mi
Registration #11	2016-05-20	45.277 mi
Registration #12	2017-05-20	45.277 mi
Registration #13	2018-05-20	45.277 mi
Registration #14	2019-05-20	45.277 mi
Registration #15	2020-05-20	45.277 mi
Registration #16	2021-05-20	45.277 mi
Registration #17	2022-05-20	45.277 mi
Registration #18	2023-05-20	45.277 mi
Registration #19	2023-06-23	45.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Kerb weight	1385 kg
Max. allowed weight	1757 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	BFS 036435