



WF56EFJ

report date: 2024-03-28

General information

Make	FORD
Model	FOCUS C-MAX TITANIUM 136
Colour	Grey
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg






Internet history

Entry 1

Date	2021-07-27
Pictures	15
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #21	2021-07-14 09:02
MOT test number	314705246435
Result	✓ Passed
Next expiry date	2022-07-13
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #20	2021-07-14 09:02
MOT test number	379518902815
Result	✗ Failed
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #19	2020-03-03 17:35
MOT test number	726617286564
Result	✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread And rear (0.1 (b))
Advice	Front and rear suspension components corroding
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Advice	Exhaust has a minor leak of exhaust gases Centre (6.1.2 (a))
Advice	Offside Front Tyre slightly damaged/cracking or perishing Outer side wall (5.2.3 (d) (ii))

**MOT #18**

2020-03-02 17:16

MOT test number

865026433225

Result**✗ Failed****Advice** Offside Rear Nail in tyre**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Fail** Brake performance not tested (1.2.1 (g))**Fail** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Exhaust has a minor leak of exhaust gases Centre (6.1.2 (a))**Advice** Offside Front Tyre slightly damaged/cracking or perishing Outer side wall (5.2.3 (d) (ii))**Fail** Nearside Rear Brake lever has insufficient reserve travel (1.1.2 (a))**Advice** Front and rear suspension components corroding**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Advice** Front Registration plate deteriorated but not likely to be misread And rear (0.1 (b))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #17**

2019-02-07 14:29

MOT test number

797074574730

Result**✓ Passed****Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened slight grooving (1.1.14 (a) (ii))**Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened slight grooving (1.1.14 (a) (ii))

**MOT #16**

2019-02-07 10:33

MOT test number

193199487731

Result

✗ Failed

Fail Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm worn edges (5.2.3 (e))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened slight grooving (1.1.14 (a) (ii))

Fail Nearside Rear Service brake excessively binding (1.2.1 (f))

Fail Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm worn edges (5.2.3 (e))

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Minor Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened slight grooving (1.1.14 (a) (ii))

Fail Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

MOT #15

2018-02-15 10:19

MOT test number

914599728011

Result

✓ Passed

Advice Nearside Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #14

2018-02-14 09:28

MOT test number

871492645778

Result

✗ Failed

Fail Offside Rear Seat belt damaged sufficient to significantly weakened the webbing (5.2.2a)

Fail Offside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)

Fail Offside Front Steering system has excessive free play detected at the steering wheel (steering rack fitted) rack end (2.2.A.1b)

Advice Nearside Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #13** 2017-02-24 11:36**MOT test number** 976419030155**Result** ✓ Passed**MOT #12** 2017-02-23 09:55**MOT test number** 273366262441**Result** ✗ Failed

- Fail** Nearside Front Headlamp aim not tested (1.8.A.1c)
- Fail** Nearside Front Steering system has excessive free play detected at the steering wheel (steering rack fitted) rack end worn (2.2.A.1b)
- Fail** Brake pedal creeps down when held under pressure (3.3.B.1a)
- Fail** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Offside Front Headlamp aim not tested (1.8.A.1c)
- Fail** Offside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)
- Fail** Brake pedal spongy (3.3.B.1b)
- Fail** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT #11 2016-03-18 10:38**MOT test number** 759967341423**Result** ✓ Passed**MOT #10** 2016-03-18 10:38**MOT test number** 581961162524**Result** ✗ Failed

- Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)
- Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)

**MOT #9** 2015-03-03 08:37**MOT test number** 287962765071**Result** ✓ Passed**MOT #8** 2015-03-02 14:37**MOT test number** 187121065034**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)**Fail** Nearside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)**Fail** Offside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)**MOT #7** 2014-02-28 11:50**MOT test number** 185749654036**Result** ✓ Passed**MOT #6** 2013-02-14 09:23**MOT test number** 229245443029**Result** ✓ Passed**MOT #5** 2012-01-11 10:34**MOT test number** 606371012093**Result** ✓ Passed**Notice** Advise handbrake button missing

**MOT #4** 2012-01-11 10:34**MOT test number** 196371912441**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Notice** Advise handbrake button missing**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**MOT #3** 2011-01-12 10:23**MOT test number** 108712711086**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-01-16 11:58**MOT test number** 673856310049**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2010-01-16 11:04**MOT test number** 114966610491**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-29
Current registration	 *****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-01-29
Last registration	2021-07-14
Complete history	See info



Registration #1	2007-01-29	24 mi
Registration #2	2010-01-16	24.840 mi
Registration #3	2010-01-16	24.840 mi
Registration #4	2011-01-12	33.005 mi
Registration #5	2012-01-11	43.180 mi
Registration #6	2013-02-14	52.409 mi
Registration #7	2014-02-28	59.695 mi
Registration #8	2015-03-02	66.557 mi
Registration #9	2015-03-03	66.557 mi
Registration #10	2016-03-18	75.105 mi
Registration #11	2016-03-18	75.105 mi
Registration #12	2016-03-18	75.105 mi
Registration #13	2016-03-18	75.105 mi
Registration #14	2016-03-18	75.105 mi
Registration #15	2016-03-18	75.105 mi
Registration #16	2016-03-18	75.105 mi
Registration #17	2016-03-18	75.105 mi
Registration #18	2016-03-18	75.105 mi
Registration #19	2016-03-18	75.105 mi
Registration #20	2016-03-18	75.105 mi
Registration #21	2016-03-18	75.105 mi
Registration #22	2016-03-18	75.105 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1825 mm
Height	1588 mm
Length	4372 mm
Wheel base	2640 mm
Max. allowed weight	1990 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	7U65429