





report date: 2024-03-29

General information

Make	ТОУОТА
Model	PRIUS VVT-I BUSINESS EDITION PLUS
Colour	Blue
Year of manufacture	2016
Top speed	112 mph
Gearbox	1 speed CVT

Engine & fuel consumption

Power	121 BHP
Max. torque	163 Nm at 3.600 rpm
Engine capacity	1.798 сс
Cylinders	4
Fuel type	Hybrid / Electric
Consumption combined	85.6 mpg
CO2 emission	76 g/km
CO2 label	А



CarCheck.co.uk page 1/13



report date: 2024-03-29


Internet history

Entry 1

Date 2021-07-10

Pictures 28

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2025-01-24
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	16
Total items failed	7

MOT #14	2024-01-25 13:48
MOT test number	851009247176
Result	✓ Passed
Next expiry date	2025-01-24

MOT #13	2024-01-25 11:34
MOT test number	545936157825
Result	X Failed
Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	

MOT #12		2023-07-28 11:23
MOT test	number	628265231849
Result		✓ Passed
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge edge plus tread lift	ted (5.2.3 (e))
Minor	Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorate	ed (5.3.4 (b) (i))
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge plus tread l	ifted (5.2.3 (e))

MOT #11	2023-01-31 10:56
MOT test number	157969360390
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT test number
688712297149

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Nail in tyre not repairable

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2022-08-04 08:11 **MOT** test number 209197809346 Result × Failed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Rear Nail in tyre not repairable Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #8	2022-02-07 16:55
MOT test number	211949839576
Result	✓ Passed
MOT #7	2022-02-07 09:21
MOT test number	947019704467
Result	× Failed
Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #6

MOT test number

Result

MOT #5

2021-08-09 11:41

211064080367

211064080367

2021-03-25 08:53

MOT test number 302665097446

Result Passed

Advice Nearside Front Tyre slightly damaged side wall damaged (5.2.3 (d) (ii))

MOT #4 2021-03-24 09:14

MOT test number 754759025585

Result X Failed

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Front Tyre slightly damaged side wall damaged (5.2.3 (d) (ii))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #3 2020-03-02 12:21

MOT test number 570988621389

Advice Outdstanding re call noticed

MOT #2 2020-03-02 09:23

MOT test number 997208296097

Result X Failed

Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

Advice Offside Rear Nail in tyre

Advice Outdstanding re call noticed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #1 2019-03-11 12:33

MOT test number 230874428026

Result ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	24 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

\sim		
Owner	hictor	7
OWITCE	HIJLOH	٧

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full it	

THE STATE OF THE S	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	OK SIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2016-03-03
Last registration	2024-01-25
Complete history	See info



Registration #1	2016-03-03	10 mi
Registration #2	2019-03-11	49.786 mi
Registration #3	2020-03-02	65.156 mi
Registration #4	2020-03-02	65.156 mi
Registration #5	2021-03-24	75.653 mi
Registration #6	2021-03-25	75.711 mi
Registration #7		11.777 es
Registration #8	2021-08-09	78.931 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		11.777 es

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 12/13



GX16ZMZ report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	92%
Children	82%
Pedestrian	77%
Safety systems	85%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1760 mm
Height	1470 mm
Length	4540 mm
Wheel base	2700 mm
Kerb weight	1375 kg
Max. allowed weight	1790 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles 2

Engine number 2ZRR803281