






report date: 2024-03-29

### General information

| Make                | VAUXHALL                      |
|---------------------|-------------------------------|
| Model               | CORSA GRIFFIN S/S SRI NAV S/S |
| Colour              | Black                         |
| Year of manufacture | 2019                          |
| Top speed           | 109 mph                       |
| Gearbox             | 5 speed Manual                |

# Engine & fuel consumption

| Power                | 89 BHP              |
|----------------------|---------------------|
| Max. torque          | 130 Nm at 4.000 rpm |
| Engine capacity      | 1.398 сс            |
| Cylinders            | 4                   |
| Fuel type            | Petrol              |
| Consumption combined | 44.8 mpg            |
| CO2 emission         | 123 g/km            |
| CO2 label            | D                   |



CarCheck.co.uk page 1/10



report date: 2024-03-29

### Internet history

### Entry 2

Date 2021-09-26

Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

| Date          | 2021-09-25  |
|---------------|-------------|
| Pictures      | 0           |
| Listing price | View report |

source: heycar.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-29

# MOT history

| MOT expiry date    | 2024-09-04 |
|--------------------|------------|
| MOT pass rate      | 67 %       |
| MOT passed         | 2          |
| Failed MOT tests   | 1          |
| Total advice items | 6          |
| Total items failed | 2          |

| MOT #3   | 2023-09-05 15:23                |
|--|---------------------------------|
| MOT test number  | 842915207378                    |
| Result   | <b>✓</b> Passed                 |
| Next expiry date   | 2024-09-04                      |
| Minor Nearside Front Lower Windscreen damaged but not adversely affect | ing driver's view (3.2 (a) (i)) |

| MOT #2  | 2023-09-05 08:24 |
|---|------------------|
| MOT test number   | 328772455740     |
| Result  | <b>X</b> Failed  |
| Fail Windscreen washer provides insufficient washer liquid both (3.5 (a))                             |                  |
| Minor Nearside Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |                  |
| Advice Nearside Front Nail in tyre  |                  |
| Fail Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))                   |                  |

| MOT #1   |  | 2022-08-08 08:32 |
|--|--|------------------|
| MOT test   | number   | 443254698078     |
| Result   |  | ✓ Passed         |
| Advice   | Nearside Rear Nail in tyre   |                  |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge 3 mm195/55/16 87H Continental. (5.2.3 (e)) |  | 87H Continental. |
| Advice   | Offside Front Tyre worn close to legal limit/worn on edge 3 mm (5.2.3 (e)) |                  |

CarCheck.co.uk page 3/10



report date: 2024-03-29

### Tax & MOT check





Expires: 4 September 2024

| Tax status       | Valid until 1 November |
|------------------|------------------------|
| Days left        | 185                    |
| MOT expiry date  | 4 September 2024       |
| Full MOT history | See MOT history        |

### Tax calculation

| Vehicle class                 | 48         |
|-------------------------------|------------|
| Band                          | G          |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months)     | £ 180,00,- |
| Standard rate (6 months)      | £ 99,00,-  |
| Premium rate (12 months)      | £ 570,00,- |
| Premium rate (6 months)       | £ 313,50,- |
|                               |            |

CarCheck.co.uk page 4/10



report date: 2024-03-29

#### Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date


Category

Type

Damage 2

Date

Category Type



#### Extra VAUXHALL salvage check



CarCheck.co.uk

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

page 5/10



AU69XAA report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



AU69XAA report date: 2024-03-29

Owner history

| Owner history  |  |
|--|--|
| For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloaner. |  |
| ********   |  |
| ***************************************  |  |
| ***************************************  |  |
| 20000000   |  |
|  |  |
| ***************************************  |  |
|  | More info >  |
| Plate changes  |  |
| See in this check if this VAUXHALL had different number plates.  |  |
| Number of plates   | ,  |
| Current registration   | NE NE  |
| Plate since  |  |
| Current registration   | AIN ON THE STATE OF THE STATE O |
| Plate since  |  |
|  | More info >  |
|  |  |
|  |  |

CarCheck.co.uk page 7/10



report date: 2024-03-29

#### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
|                   |  |

**Contact info** 

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-29

# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 6          |
| First mileage registration | 2019-09-05 |
| Last registration          | 2023-09-05 |
| Complete history           | See info   |



| Registration #1 | 2019-09-05 | 16 mi     |
|-----------------|------------|-----------|
| Registration #2 |            | 77,777 66 |
| Registration #3 |            | 11.777 es |
| Registration #4 |            | 71.777 66 |
| Registration #5 |            | 9.77 sc   |
| Pogistration #6 |            |           |

Registration #6

More info >

CarCheck.co.uk page 9/10



AU69XAA report date: 2024-03-29

# Safety ratings

| NCAP rating    | ***             |
|----------------|-----------------|
| Adult          | 79%             |
| Children       | 77%             |
| Pedestrian     | 71%             |
| Safety systems | 56%             |
| Overall rating | 72%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 1746 mm |
|---------------------|---------|
| Height              | 1481 mm |
| Length              | 4021 mm |
| Max. allowed weight | 1630 kg |

### Additional information

| Number of seats | 5                   |
|-----------------|---------------------|
| Number of axles | 2                   |
| Engine number   | B14XER -19WB8076LDD |

CarCheck.co.uk page 10/10