





report date: 2024-03-29

General information

Make	VOLVO
Model	XC60
Colour	Grey
Year of manufacture	2018
Top speed	140 mph
0 - 60 mph	5.2 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	303 BHP
Max. torque	400 Nm at 4.800 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Hybrid / Electric
CO2 emission	55 g/km
CO2 label	A



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date	2022-01-26
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/11



GN68LCA report date: 2024-03-29

MOT history

MOT expiry date	2024-10-23
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #4	2023-10-05 11:07
MOT test number	821242211430
Result	✓ Passed
Next expiry date 2024-10-	
Advice Offside Front Tyre worn close to legal limit/worn on edge 3.4mm on inner edge (5.2.3 (e))	

MOT #3		2022-10-13 08:52
MOT test	number	696380586180
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #2		2021-10-20 13:19
MOT test	number	197466139374
Result		✓ Passed
Advice	Under trays fitted	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge slight side wall dam	age (5.2.3 (e))
Advice	Road wheel slightly distorted all (5.2.2 (c) (i))	
Minor	Windscreen damaged but not adversely affecting driver's view chipped (3.2 (a)	(i))

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #1 2021-10-20 08:05

MOT test number 779725829156

Result

× Failed

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords sidewall 255/40/21 102V (5.2.3 (d) (i))

Advice

Nearside Rear Tyre slightly damaged getting low slight side wall damage (5.2.3 (d) (ii))

Minor

Windscreen damaged but not adversely affecting driver's view chipped (3.2 (a) (i))

Advice

Under trays fitted

Advice

Road wheel slightly distorted all (5.2.2 (c) (i))

Fail

Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

CarCheck.co.uk page 4/11



GN68LCA report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	23 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	С
First licence fee (12 months)	£ 2,00,-
Standard rate (12 months)	£ 170,00,-
Standard rate (6 months)	£ 93,50,-
Premium rate (12 months)	£ 560,00,-
Premium rate (6 months)	£ 308,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full it		

	More info >	
Plate changes		
See in this check if this VOLVO had different number plates.		
Number of plates		
Current registration	NE OK	
Plate since		
Current registration	NE UK	
Plate since		
	More info >	

CarCheck.co.uk page 8/11



GN68LCA report date: 2024-03-29

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-10-24
Last registration	2023-10-05
Complete history	See info



Registration #1	2018-10-24	15 mi
Registration #2	2021-10-20	57.218 mi
Registration #3	2021-10-20	57.218 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		0.77

More info >

page 10/11 CarCheck.co.uk




report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	98%
Children	87%
Pedestrian	76%
Safety systems	95%
Overall rating	90%
Video	see crash video



Dimensions & weight

Width	2117 mm
Height	1658 mm
Length	4688 mm
Wheel base	2865 mm
Kerb weight	2110 kg
Max. allowed weight	2660 kg

Additional information

Fuel tank capacity	71	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 11,	/11