





#### General information

Make	FIAT
Model	PANDA EASY
Colour	Purple
Year of manufacture	2014
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	120 g/km
CO2 label	С







# Internet history

Entry 3	
Date	2021-12-13
Pictures	12
Listing price	View report



source: autotrader.co.uk

Entry 2	
Date	2021-07-23
Pictures	42
Listing price	View report



source: yesauto.com

Entry 1	
Date	2021-07-20
Pictures	12
Listing price	View report



source: cargurus.co.uk



### MOT history

MOT expiry date	2023-09-21
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	8
Total items failed	4

MOT #7	2022-09-22 13:11
MOT test number	284210507335
Result	✓ Passed
Next expiry date	2023-09-21

МОТ #6	2021-09-14 15:29
MOT test number	784352140642
Result	✓ Passed

MOT #5	2020-10-27 16:54
MOT test number	168122047852
Result	✓ Passed
Advice Exhaust mounting defective Down pipe (6.1.2 (a))	



MOT #4	2020-10-26 11:16
MOT test number	395688960235
Result	🗙 Failed
<b>Advice</b> Nearside Front Brake disc worn, pitted or scored, but not seriously weakened work on inner edge/face (1.1.14 (a) (ii))	/ery poor condition
Advice Front Brake pad(s) wearing thin Requires further investigation (1.1.13 (a) (ii))	
Advice Exhaust mounting defective Down pipe (6.1.2 (a))	
<b>Fail</b> Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the (5.2.3 (d) (i))	he ply or cords
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened Ve inner edge/face (1.1.14 (a) (ii))	ry poor condition on
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))	
<b>Fail</b> Nearside Front Tyre has a cut in excess of the requirements deep enough to reach (5.2.3 (d) (i))	n the ply or cords
<b>Fail</b> Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach (5.2.3 (d) (i))	the ply or cords

MOT #3	2	019-07-29 12:59
MOT test	number	586471107456
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Rear Tyre worn close to legal limit/worn on edge 185/55/15 (5.2.3 (e))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #2	2018-07-23 13:54
MOT test number	132557666335
Result	✓ Passed

MOT #1	2017-07-24 09:33
MOT test number	412941697575
Result	✓ Passed



Tax & MOT check

X Untaxed Tax expired: 1 December 2023	<b>X</b> <b>MOT</b> Expired: 21 September 2023
Tax status	Expired at 1 December 2023
Days left	151 days too late
MOT expiry date	21 September 2023
Full MOT history	See MOT history
Tax calculation	
Vehicle class	48
Band	C

Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4. ARMPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

#### Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





### Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	
***********	
*******	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Carrent registration Plate since	





#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



GL14NWB report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-07-28
Last registration	2022-09-22
Complete history	See info



Registration #1	2014-07-28	18 mi
Registration #2	2017-07-24	43.579 mi
Registration #3	2018-07-23	50.634 mi
Registration #4	2019-07-29	56.536 mi
Registration #5	2020-10-26	61.835 mi
Registration #6	2020-10-27	61.835 mi
Registration #7		11.117 esi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.117 esi





## Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	see crash video



Dimensions & weight	
Width	1643 mm
Height	1551 mm
Length	3653 mm
Wheel base	2300 mm
Kerb weight	1015 kg
Max. allowed weight	1420 kg
Additional information	
Fuel tank capacity	37
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 11/11

Number of axles	2
Engine number	0839737