





report date: 2024-03-29

General information

Make	FIAT
Model	DOBLO 16V MULTIJET
Colour	White
Year of manufacture	2015
Top speed	97 mph
0 - 60 mph	14.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	200 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	133 g/km
CO2 label	E



CarCheck.co.uk page 1/11




Internet history

Entry 1

Date 2021-07-28

Pictures 1

Listing price <u>View report</u>



source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2023-04-23
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #5		2022-04-23 10:09
MOT test	number	558490103476
Result		✓ Passed
Next exp	iry date	2023-04-23
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorate	ted (6.1.7 (g) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1	14 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4		2022-04-23 10:09
MOT test number		482211509699
Result		≍ Failed
Advice Offside Rear Tyre	worn close to legal limit/worn on edge (5.2.3 (e	e))
Pass with rectification	Offside Front Headlamp not working on main b	eam (4.1.1 (a) (ii))
Advice Nearside Rear Tyre	e worn close to legal limit/worn on edge (5.2.3	(e))
Minor Nearside Front Driv	e shaft joint constant velocity boot severely de	eteriorated (6.1.7 (g) (i))
Advice Oil leak, but not ex	xcessive (8.4.1 (a) (i))	
Advice Front Brake disc w	orn, pitted or scored, but not seriously weaker	ned (1.1.14 (a) (ii))

CarCheck.co.uk page 3/11



Result

BV15ATK report date: 2024-03-29

✓ Passed

MOT #3 2021-04-24 08:59

MOT test number 914924882465

Result ✓ Passed

MOT #2 2019-06-11 10:21

MOT test number 360454221111

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Inner Tyre worn close to legal limit/worn on edge both side (5.2.3 (e))

MOT #1 2018-05-18 08:31

MOT test number 900823068396

CarCheck.co.uk page 4/11



Tax & MOT check



Tax expired: 30 September 2022



Expired: 23 April 2023

Tax status	Expired at 30 September
Days left	578 days too late
MOT expiry date	23 April 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11



BV15ATK

report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

o mile motory	
For how long did the current and previous owner(s) have this FIAT? How many owners did check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
See in this check if this FIAT had different humber plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



BV15ATK

report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2015-04-30
Last registration	2022-04-23
Complete history	See info



Registration #1	2015-04-30	7 mi
Registration #2	2018-05-18	90.267 mi
Registration #3	2019-06-11	119.445 mi
Registration #4	2021-04-24	119.356 mi
Registration #5		11.777 es
Registration #6		71.777 66
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditionin
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	★★★ ★★
Video	see crash video



Dimensions & weight

Width	1832 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1345 kg
Max. allowed weight	2070 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number Carcheck.co.uk	5755767 page 11/11