





report date: 2024-03-29

General information

Make	HONDA
Model	FR-V VTEC SE
Colour	Silver
Year of manufacture	2006
Top speed	112 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	154 Nm at 4.800 rpm
Engine capacity	1.668 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	37.7 mpg
CO2 emission	179 g/km
CO2 label	1



CarCheck.co.uk page 1/14



EN06UCY report date: 2024-03-29

Internet history

F		7
En	ITTV	т.

ciitiy 1	
Date	2021-10-01
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

N/I	α		TC:	-	r\/
101	•		115		ıv
	•	Γh			. ,

MOT expiry date	2024-09-29
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	30
Total items failed	8

MOT #19	2023-09-29 12:26
MOT test number	154219454281
Result	✓ Passed
Next expiry date	2024-09-29

MOT #18	2022-09-30 12:06
MOT test number	357681834346
Result	✓ Passed

MOT #17		2021-09-29 15:36
MOT test	number	500105946662
Result		✓ Passed
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #16	2019-12-09 16:25
MOT test number	768563861398
Result	✓ Passed
Advice N/s front tyre feathering on edges	

CarCheck.co.uk page 3/14



Result

EN06UCY

report date: 2024-03-29

× Failed

MOT test number

Result

Fail Offside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

Fail Nearside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

Advice N/s front tyre feathering on edges

 MOT #14
 2018-12-03 16:10

 MOT test number
 242109833624

Result ✓ Passed

MOT #13 2018-12-03 09:50

MOT test number 322833721696

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12 2017-12-08 16:59

MOT test number 745470788660

Result

Passed

MOT #11 2016-12-03 11:58

MOT test number 738118191265

Result ✓ Passed

Advice Child Seat fitted not allowing full inspection of adult belt

Advice Rear coil springs corroded

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/14



report date: 2024-03-29



MOT #9	2015-12-04 16:36
MOT test number	832053158999
Result	X Failed
Advice Baby seat in rear	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Exhaust system not adequately supported middle box (7.1.1)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #8		2014-11-29 13:40
MOT test	number	626583634373
Result		✓ Passed
Advice	Nearside Rear coil spring corroded (2.4.C.1b)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear coil spring corroded (2.4.C.1b)	
Notice	Oil leak	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #7 2013-12-02 15:41

MOT test number 718136133344

MOT #6 2013-12-02 12:29

MOT test number 409586033363

Result X Failed

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

Fail Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #5 2012-12-06 10:33

MOT test number 527641642342

Result \rightarrow Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #4 2012-12-05 10:52

MOT test number 878550642302

Result X Failed

Fail Front Brake pedal anti-slip provision incomplete (3.3.A.1b)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)

Notice Clutch pedal rubber worn

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #3	2011-08-11 13:33
MOT test number	487263321206
Result	✓ Passed
Notice Stop lamp bulb 1036	
Advice Front Brake pad(s) wearing thin (3.5.1g)	

MOT #2	2010-07-20 10:07
MOT test number	981961000220
Result	✓ Passed
MOT #1	2009-07-20 14:48
MOT test number	582581109227
Result	✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check



MOT

Tax status	Valid until 1 February
Days left	278
MOT expiry date	29 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



factor scincol

EN06UCY

report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this HONDA had different number plates. deer of plates

CarCheck.co.uk page 11/14



EN06UCY report date: 2024-03-29

Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-07-18
Last registration	2023-09-29
Complete history	See info



Registration #1	2006-07-18	12 mi
Registration #2	2009-07-20	46.123 mi
Registration #3	2010-07-20	53.855 mi
Registration #4	2011-08-11	67.817 mi
Registration #5	2012-12-05	80.728 mi
Registration #6	2012-12-06	80.744 mi
Registration #7	2013-12-02	87.370 mi
Registration #8	2013-12-02	87.370 mi
Registration #9	2014-11-29	94.628 mi
Registration #10	2015-12-04	100.651 mi
Registration #11	2015-12-05	100.651 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		77.777-00

More info >

CarCheck.co.uk page 13/14



EN06UCY report date: 2024-03-29

Safety ratings

NCAP rating	十十六
-------------	-----

Video <u>see crash video</u>



Dimensions & weight

Width	2113 mm
Height	1610 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1397 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	6
Engine number	D17A25303698

CarCheck.co.uk page 14/14