



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	IQ VVT-I IQ
Colour	Blue
Year of manufacture	2010
Top speed	93 mph
0 - 60 mph	14.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	91 Nm at 4.800 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	57.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 3


Date	2024-02-10
Pictures	27
Listing price	View report



source: cargurus.co.uk

Entry 2


Date	2021-10-26
Pictures	8
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-26
Pictures	8
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-25
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	25
Total items failed	6

MOT #16	2023-06-26 16:28
MOT test number	136714552266
Result	✓ Passed
Next expiry date	2024-06-25
Advice	Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #15**

2023-05-22 16:02

MOT test number

750794151221

Result**✗ Failed****Advice** Nearside Rear Brake hose has slight corrosion to ferrule x2 hoses (1.1.12 (f) (i))**Advice** Offside Rear Brake hose has slight corrosion to ferrule x2 hoses (1.1.12 (f) (i))**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #14**

2021-11-15 09:37

MOT test number

171602513503

Result**✓ Passed****MOT #13**

2021-03-02 11:57

MOT test number

312457870861

Result**✓ Passed****MOT #12**

2020-03-12 11:18

MOT test number

479754085054

Result**✓ Passed****Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #11** 2020-03-12 11:15**MOT test number** 927528256363**Result** ✗ Failed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #10** 2019-03-13 11:10**MOT test number** 120931144139**Result** ✓ Passed**MOT #9** 2019-03-07 16:16**MOT test number** 188226302691**Result** ✗ Failed**Fail** Offside Rear Service brake excessively fluctuating (1.2.1 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #8** 2018-03-08 15:24**MOT test number** 857138200372**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2018-03-07 15:28**MOT test number** 336710357128**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2017-03-09 11:30**MOT test number** 187006947013**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2017-03-09 10:29**MOT test number** 173276566924**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2016-03-23 10:08**MOT test number** 729568994003**Result** ✓ Passed**MOT #3** 2015-03-03 16:13**MOT test number** 258182265052**Result** ✓ Passed



MOT #2	2014-03-17 11:42
MOT test number	509786674042
Result	✓ Passed

MOT #1	2013-03-25 09:39
MOT test number	989664283030
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
25 June 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	25 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	YH10TZA
Plate since	2019-09-29
Current registration	YH10TZA
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-03-31
Last registration	2023-06-26
Complete history	See info



Registration #1	2010-03-31	24 mi
Registration #2	2013-03-25	8.293 mi
Registration #3	2014-03-17	8.775 mi
Registration #4	2015-03-03	13.520 mi
Registration #5	2016-03-23	16.001 mi
Registration #6	2017-03-09	18.451 mi
Registration #7	2017-03-09	18.451 mi
Registration #8	2018-03-07	22.254 mi
Registration #9	2018-03-08	22.256 mi
Registration #10	2019-03-07	25.047 mi
Registration #11	2019-03-07	25.047 mi
Registration #12	2019-03-07	25.047 mi
Registration #13	2019-03-07	25.047 mi
Registration #14	2019-03-07	25.047 mi
Registration #15	2019-03-07	25.047 mi
Registration #16	2019-03-07	25.047 mi
Registration #17	2019-03-07	25.047 mi
Registration #18	2019-03-07	25.047 mi
Registration #19	2019-03-07	25.047 mi
Registration #20	2019-03-07	25.047 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1680 mm
Height	1500 mm
Length	2985 mm
Wheel base	2000 mm
Kerb weight	845 kg
Max. allowed weight	1215 kg

Additional information

Fuel tank capacity	32 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Engine number	1KR0998678
---------------	------------