



report date: 2024-03-28

General information

Make	CITROEN
Model	BERLINGO HDI 600 ENTERPRISE SWB H/C CDV
Colour	Silver
Year of manufacture	2007
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	170 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2024-08-08
MOT pass rate	61 %
MOT passed	14
Failed MOT tests	9
Total advice items	77
Total items failed	22

MOT #23	2023-08-09 07:29
MOT test number	726724342261
Result	✓ Passed
Next expiry date	2024-08-08
Advice	Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
Advice	Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #22**

2022-02-09 16:40

**MOT test number**

698984319416

**Result**

✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Inner tyre side wall (5.2.3 (d) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Engine oil leak
- Minor** Nearside Windscreen damaged but not adversely affecting driver's view Stone chip (3.2 (a) (i))
- Advice** Exhaust noisy Noisier than similar vehicle fitted with standard silencer in average condition (8.1.1 (a))
- Advice** Cam belt replacement may be over due (Every 10 years)
- Minor** Nearside Front Upper Windscreen damaged but not adversely affecting driver's view Large crack (3.2 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material Slightly corroded (1.1.11 (c))
- Advice** Spare tyre is void of tread

**MOT #21**

2022-02-07 12:15

**MOT test number**

665419932540

**Result**

✗ Failed

**Advice** Exhaust noisy Noisier than similar vehicle fitted with standard silencer in average condition (8.1.1 (a))

**Advice** Cam belt replacement may be over due (Every 10 years)

**Minor** Nearside Front Upper Windscreen damaged but not adversely affecting driver's view Large crack (3.2 (a) (i))

**Advice** Offside Front Brake pipe corroded, covered in grease or other material Slightly corroded (1.1.11 (c))

**Advice** Spare tyre is void of tread

**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

**Fail** Offside Fuel pipe leaking Under body fuel cooler system (6.1.3 (b) (i))

**Advice** High level brake light stays on all the time

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Engine oil leak

**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Inner tyre side wall (5.2.3 (d) (ii))

**Minor** Nearside Windscreen damaged but not adversely affecting driver's view Stone chip (3.2 (a) (i))

**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

**Fail** Exhaust emissions exceed manufacturer's specified limit 1.4 (8.2.2.2 (a))

**MOT #20**

2021-01-12 09:45

**MOT test number**

801600890556

**Result**

✓ Passed

**Advice** Rear Exhaust silencer in poor condition

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #19**

2021-01-11 12:08

**MOT test number**

443876792668

**Result****✗ Failed****Advice** Rear Exhaust silencer in poor condition**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Driver's door cannot be opened from outside the vehicle (6.2.3 (a))**Advice** Front Brake pads worn low**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Central Rear Stop lamp(s) with a multiple light source more than 1/2 not functioning (4.3.1 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #18**

2020-01-14 10:41

**MOT test number**

353418042190

**Result**

✓ Passed

- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge bald on inner edge, 2mm on outer (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge bald on inner & outer edges (5.2.3 (e))
- Advice** Rear silencer outer casing & support band badly corroded
- Advice** Items removed from driver's view prior to test
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge bald on inner edge, 2mm on outer (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge bald on inner & outer edges (5.2.3 (e))
- Advice** Oil leak, but not excessive from offside engine area (8.4.1 (a) (i))

**MOT #17**

2020-01-14 10:41

**MOT test number**

822315719215

**Result**

✗ Failed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge bald on inner edge, 2mm on outer (5.2.3 (e))

**Advice** Items removed from driver's view prior to test

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge bald on inner & outer edges (5.2.3 (e))

**Pass with rectification** Headlamp aim too high both (4.1.2 (a))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge bald on inner edge, 2mm on outer (5.2.3 (e))

**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge bald on inner & outer edges (5.2.3 (e))

**Advice** Oil leak, but not excessive from offside engine area (8.4.1 (a) (i))

**Advice** Rear silencer outer casing & support band badly corroded

**MOT #16**

2019-01-09 10:36

**MOT test number**

943427083233

**Result**

✓ Passed

**Advice** Oil leak, but not excessive from behind alternator area (8.4.1 (a) (i))

**Advice** Rear silencer outer casing corroded through

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both worn & badly corroded on inner faces (1.1.14 (a) (ii))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #15**

2019-01-09 10:36

**MOT test number**

659974090513

**Result****✗ Failed****Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both worn & badly corroded on inner faces (1.1.14 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Pass with rectification** Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))**Advice** Oil leak, but not excessive from behind alternator area (8.4.1 (a) (i))**Advice** Rear silencer outer casing corroded through**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #14**

2018-01-26 08:34

**MOT test number**

674814031376

**Result****✓ Passed****Advice** Exhaust box end has slightly corroded, belt holder has slightly damage**Advice** Front brake disc worn, pitted or scored, but not seriously weakened have slight lipped both sides (3.5.1i)**MOT #13**

2018-01-24 12:02

**MOT test number**

687026185827

**Result****✗ Failed****Fail** Offside Front Lower Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Exhaust box end has slightly corroded, belt holder has slightly damage**Advice** Front brake disc worn, pitted or scored, but not seriously weakened have slight lipped both sides (3.5.1i)



**MOT #12** 2017-03-15 10:15**MOT test number** 363540112775**Result** ✓ Passed**Advice** N/s/r tyre slightly wearing worn ,few cuts,inner sidewall slightly perished**Advice** O/s/r tyre on inner edge has nail**Advice** Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Exhaust end box slightly corroded**MOT #11** 2016-07-04 12:05**MOT test number** 577786117401**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2015-07-06 10:15**MOT test number** 386277585117**Result** ✓ Passed**Notice** Nearside gearbox differential oil seal leaking**MOT #9** 2015-07-06 10:15**MOT test number** 298517085401**Result** ✗ Failed**Pass with rectification** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Notice** Nearside gearbox differential oil seal leaking**MOT #8** 2014-07-04 08:59**MOT test number** 238255884481**Result** ✓ Passed

**MOT #7** 2013-07-02 16:06**MOT test number** 226803783124**Result** ✓ Passed**Notice** O/s front tyre wearing on inner and outer edges**Notice** Items removed from driver's view prior to test**Notice** N/s front tyre wearing on inner and outer edges**MOT #6** 2013-07-02 12:48**MOT test number** 357293283147**Result** ✗ Failed**Notice** Items removed from driver's view prior to test**Fail** Nearside Rear Braking system leaking (3.6.A.1)**Notice** N/s front tyre wearing on inner and outer edges**Notice** O/s front tyre wearing on inner and outer edges**Fail** Brakes imbalanced across an axle (3.7.B.5b)**MOT #5** 2012-07-03 13:49**MOT test number** 498525382103**Result** ✓ Passed**MOT #4** 2012-07-03 09:24**MOT test number** 219005882171**Result** ✗ Failed**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)



MOT #3	2011-06-29 11:58
MOT test number	777690481164
Result	✓ Passed
MOT #2	2010-06-07 12:20
MOT test number	590828850197
Result	✓ Passed
MOT #1	2010-06-07 09:06
MOT test number	120058050182
Result	✗ Failed
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)



Tax & MOT check

✓  
Taxed

Tax due:  
1 December 2024

✓  
MOT

Expires:  
8 August 2024

Tax status		Valid until 1 December
Days left		217
MOT expiry date		8 August 2024
Full MOT history		<a href="#">See MOT history</a>



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>BT07ZNE</b>
Plate since	2019-03-28
Current registration	<b>BT07ZNE</b>
Plate since	2019-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >





Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-06-28
Last registration	2023-08-09
Complete history	<a href="#">See info</a>



Registration #1	2007-06-28	29 mi
Registration #2	2010-06-07	29.279 mi
Registration #3	2010-06-07	29.283 mi
Registration #4	2011-06-29	33.924 mi
Registration #5	2012-07-03	37.445 mi
Registration #6	2012-07-03	37.445 mi
Registration #7	2013-07-02	42.385 mi
Registration #8	2013-07-02	42.385 mi
Registration #9	2014-07-04	48.088 mi
Registration #10	2015-07-06	63.575 mi
Registration #11	2016-07-04	79.929 mi
Registration #12	2017-03-15	87.566 mi
Registration #13	2018-03-20	95.277 mi
Registration #14	2018-03-20	95.277 mi
Registration #15	2018-03-20	95.277 mi
Registration #16	2018-03-20	95.277 mi
Registration #17	2018-03-20	95.277 mi
Registration #18	2018-03-20	95.277 mi
Registration #19	2018-03-20	95.277 mi
Registration #20	2018-03-20	95.277 mi
Registration #21	2018-03-20	95.277 mi
Registration #22	2018-03-20	95.277 mi
Registration #23	2018-03-20	95.277 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)

Dimensions & weight

Width	1724 mm
Height	1796 mm
Length	4137 mm
Wheel base	2690 mm
Kerb weight	1336 kg
Max. allowed weight	1730 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2
Engine number	JB790113629