



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT SE TDI
Colour	Blue
Year of manufacture	-
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 4.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-22
Pictures	18
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #18	2022-01-28 16:51
MOT test number	758648527307
Result	✓ Passed
Next expiry date	2023-01-31

MOT #17	2022-01-28 10:43
MOT test number	298344155395
Result	✗ Failed
<div><div>Fail</div> Tyre has ply or cords exposed both rear (5.2.3 (d) (ii))</div> <div><div>Minor</div> Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))</div>	

MOT #16	2021-02-01 14:21
MOT test number	911838066901
Result	✓ Passed
<div><div>Minor</div> Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))</div> <div><div>Advice</div> Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))</div> <div><div>Advice</div> Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))</div>	

**MOT #15**

2021-02-01 10:31

MOT test number

682296606405

Result**✗ Failed****Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #14**

2019-07-22 12:09

MOT test number

242742801471

Result**✓ Passed****MOT #13**

2019-07-19 15:21

MOT test number

387695227078

Result**✗ Failed****Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #12**

2018-05-14 12:04

MOT test number

304035207376

Result**✓ Passed****Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**MOT #11** 2018-05-14 11:26**MOT test number** 724780405834**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #10** 2017-05-05 14:02**MOT test number** 117240819102**Result** ✓ Passed**MOT #9** 2017-05-05 10:51**MOT test number** 723525588429**Result** ✗ Failed**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Nearside Side repeater not working (1.4.A.2c)**MOT #8** 2016-05-20 09:53**MOT test number** 150365639110**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit mis-shaped (4.1.E.1)**MOT #7** 2016-05-20 08:47**MOT test number** 684711715981**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit mis-shaped (4.1.E.1)

**MOT #6** 2015-06-08 15:26**MOT test number** 756259555168**Result** ✓ Passed**MOT #5** 2014-05-19 16:41**MOT test number** 379569134113**Result** ✓ Passed**Notice** N/S/R tyre cobbled on inner edge**MOT #4** 2014-05-19 14:58**MOT test number** 397139734141**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** N/S/R tyre cobbled on inner edge**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**MOT #3** 2013-06-01 09:48**MOT test number** 227992953181**Result** ✓ Passed**MOT #2** 2012-06-08 10:16**MOT test number** 337170762185**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2011-06-01 12:36**MOT test number** 368412551111**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-06-10
Last registration	2022-01-28
Complete history	See info



Registration #1	2008-06-10	21 mi
Registration #2	2011-06-01	27.099 mi
Registration #3	2012-06-08	33.916 mi
Registration #4	2013-06-01	44.824 mi
Registration #5	2014-05-19	63.636 mi
Registration #6	2014-05-19	63.636 mi
Registration #7	2015-06-08	84.185 mi
Registration #8	2016-05-20	105.194 mi
Registration #9	2016-05-20	105.194 mi
Registration #10	2017-05-05	124.049 mi
Registration #11	2018-05-20	124.049 mi
Registration #12	2019-05-20	124.049 mi
Registration #13	2020-05-20	124.049 mi
Registration #14	2021-05-20	124.049 mi
Registration #15	2022-01-28	124.049 mi
Registration #16	2022-01-28	124.049 mi
Registration #17	2022-01-28	124.049 mi
Registration #18	2022-01-28	124.049 mi
Registration #19	2022-01-28	124.049 mi
Registration #20	2022-01-28	124.049 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1454 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBA 056163