





report date: 2024-03-29

## General information

| Make                | PEUGEOT        |
|---------------------|----------------|
| Model               | 107 ACTIVE     |
| Colour              | Purple         |
| Year of manufacture | 2014           |
| Top speed           | 99 mph         |
| 0 - 60 mph          | 14.2 seconds   |
| Gearbox             | 5 speed Manual |

## Engine & fuel consumption

| Power                   | 68 BHP             |
|-------------------------|--------------------|
| Max. torque             | 93 Nm at 3.600 rpm |
| Engine capacity         | 998 сс             |
| Cylinders               | 3                  |
| Fuel type               | Petrol             |
| Consumption city        | 55.4 mpg           |
| Consumption extra urban | 74.3 mpg           |
| Consumption combined    | 65.7 mpg           |
| CO2 emission            | 99 g/km            |
| CO2 label               | A                  |



CarCheck.co.uk page 1/11



report date: 2024-03-29

## Internet history

### Entry 1

Date 2021-12-02

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date    | 2025-01-30 |
|--------------------|------------|
| MOT pass rate      | 100 %      |
| MOT passed         | 8          |
| Failed MOT tests   | 0          |
| Total advice items | 9          |
| Total items failed | 0          |

| MOT #8  | 2024-01-19 07:29      |
|---|-----------------------|
| MOT test number   | 745881046889          |
| Result  | ✓ Passed              |
| Next expiry date  | 2025-01-30            |
| Advice Front Anti-roll bar linkage pin or bush worn but not resulting in excessive roffside (5.3.4 (a) (i)) | movement nearside and |
| Advice Rear Brake hose has slight corrosion to ferrule nearside and offside (1.1.1)                         | 2 (f) (i))            |
| Advice Engine covers and undertrays fitted  |                       |
| Advice Front Tyre slightly damaged/cracking or perishing nearside and offside (5.                           | 2.3 (d) (ii))         |

| 645533095701     |
|------------------|
| ✓ Passed         |
|                  |
| 2022-01-11 11:14 |
| 951845863469     |
| ✓ Passed         |
|                  |

| MOT #5          | 2021-01-30 08:41 |
|-----------------|------------------|
| MOT test number | 160459698901     |
| Result          | ✓ Passed         |

CarCheck.co.uk page 3/11



MOT test number

Result

Advice Front brake discs (inner faces) rusty

Advice Front lower suspension arms both rear bushes starting to deteriorate

Advice Front anti roll bar both link bushes deteriorating

| MOT #3   |  | 2019-01-31 08:46 |
|----------|--|------------------|
| MOT test | number   | 923280097545     |
| Result   |  | ✓ Passed         |
| Advice   | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |                  |
| Advice   | Offside Front Road wheel slightly distorted Outer side (5.2.2 (c) (i)) |                  |

| MOT #2          | 2017-11-15 10:09 |
|-----------------|------------------|
| MOT test number | 693465576423     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #1          | 2016-12-14 14:09 |
| MOT test number | 565098711563     |
| Result          | <b>✓</b> Passed  |

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status       | Valid until 1 March |
|------------------|---------------------|
| Days left        | 305                 |
| MOT expiry date  | 30 January 2025     |
| Full MOT history | See MOT history     |

### Tax calculation

| Vehicle class                           | 48             |
|---|----------------|
| Band                                    | A              |
| Single payment (12 months)              | £ 0,00,-       |
| Single six month payment                | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |

CarCheck.co.uk page 5/11



report date: 2024-03-29

### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

More info >

# Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this PEUGEOT had different number plates. ober of plates furthe scinors

CarCheck.co.uk page 8/11



report date: 2024-03-29

### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

## Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 10         |
| First mileage registration | 2014-01-08 |
| Last registration          | 2024-01-19 |
| Complete history           | See info   |



| Registration #1                 | 2014-01-08 | 28 mi                               |
|---------------------------------|------------|-------------------------------------|
| Registration #2                 | 2016-12-14 | 30.210 mi                           |
| Registration #3                 | 2017-11-15 | 32.192 mi                           |
| Registration #4                 | 2019-01-31 | 34.892 mi                           |
| Registration #5                 | 2020-01-30 | 36.920 mi                           |
|                                 |            |                                     |
| Registration #6                 |            | 11.777 es                           |
| Registration #6 Registration #7 |            | 11.777 es                           |
|                                 |            | 11.777 es                           |
| Registration #7                 |            | 11.777 es<br>11.777 es<br>11.777 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

## Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

## Safety ratings

| NCAP rating    | ***             |
|----------------|-----------------|
| Adult          | 68%             |
| Children       | 73%             |
| Pedestrian     | 53%             |
| Safety systems | 71%             |
| Overall rating | 66%             |
| Video          | see crash video |



## Dimensions & weight

| Width               | 1630 mm |
|---------------------|---------|
| Height              | 1465 mm |
| Length              | 3430 mm |
| Wheel base          | 2340 mm |
| Kerb weight         | 905 kg  |
| Max. allowed weight | 1190 kg |

## Additional information

| Fuel tank capacity                | 35 I                  |
|-----------------------------------|-----------------------|
| Fuel delivery                     | Multi-Point Injection |
| Number of doors                   | 5                     |
| Number of seats<br>CarCheck.co.uk | 4 page 11/11          |

Number of axles 2

**Engine number** 7552662