





## General information

Make	HYUNDAI
Model	MATRIX GSI
Colour	Silver
Year of manufacture	2006
Top speed	103 mph
Gearbox	4 speed automatic

# Engine & fuel consumption

102 BHP	0
141 Nm at 4.500 rpm	10
1.599 cc	12
4	14
Petrol	16
25.5 mpg	18
31.0 mpg	22
34.0 mpg	
198 g/km	
J	
	141 Nm at 4.500 rpm   1.599 cc   4   Petrol   25.5 mpg   31.0 mpg   34.0 mpg







# MOT history

MOT expiry date	2021-03-06
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	18
Total items failed	5

MOT #16	2020-02-28 11:12
MOT test number	864033607100
Result	✓ Passed
Next expiry date	2021-03-06

MOT #15		2020-02-28 11:12
MOT test number		254370657537
Result		🗙 Failed
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Pass with rectification	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #14	2019-03-01 15:50
MOT test number	684305776611
Result	✓ Passed
MOT #13	2018-03-03 12:31

MOT test number	517050510183
Result	✓ Passed





MOT #12		2018-03-03 12:31
MOT test number		170491064521
Result		🗙 Failed
Pass with rectification	Offside Front Tyre tread depth below require	ements of 1.6mm (4.1.E.1)
MOT #11		2017-03-02 16:44
MOT test number		221458995483
Result		✓ Passed
Advice Nearside Rear T	yre worn close to the legal limit (4.1.E.1)	
Advice Front Brake pad	(s) wearing thin (3.5.1g)	
Advice Offside Rear Tyr	e worn close to the legal limit (4.1.E.1)	

Advice Front brake disc worn, pitted or scored, but not seriously weakened Both front worn (3.5.1i)

MOT #10	2016-03-07 16:53
MOT test number	558832101159
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	

MOT #9	2016-03-07 16:53	
MOT test number	809609538840	
Result	× Failed	
Advice Front Brake pad(s) wearing thin (3.5.1g)		
Pass with rectification	Centre Front Upper Windscreen has a sticker or other obstruction encroaching	
into the swept area by more than 40mm outside zone 'A' (8.3.1e)		

MOT #8	2015-03-07 12:40
MOT test number	549506965016
Result	✓ Passed





MOT #7		2014-03-01 14:35
MOT test	number	639480264011
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front Windscreen has damage to an area less than a 40mm circle outside	zone 'A' (8.3.1d)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Nail in offside rear tyre	
MOT #6		2013-03-02 11:17

	2013 03 02 11.17
MOT test number	147071463450
Result	✓ Passed

MOT #5	2013-03-01 09:34
MOT test number	206880563048
Result	🗙 Failed
<b>Fail</b> Rear Stop lamp not working (1.2.1b)	

MOT #4	2012-03-02 14:40
MOT test number	118822262064
Result	✓ Passed

MOT #3	2011-03-04 11:56
MOT test number	186653261068
Result	✓ Passed
Advice Front Windscreen has damage to an area less than a 40mm circ	cle outside zone 'A' (8.3.1d)

MOT #2	2010-03-04 14:31
MOT test number	584213560093
Result	✓ Passed





MOT #1		2009-03-02 15:47
MOT test	number	600041069073
Result		✓ Passed
Notice	O/s/f brake pads low	
Notice	N/s/r tyre feathering on outer edge	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	N/s/f brake pads worn thin	
Notice	Front tyres worn badly on inner edges	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Front brake discs worn and lipped	



Tax & MOT check

X Untaxed Tax expired: 14 January 2021	<b>X</b> <b>MOT</b> Expired: 6 March 2021
Tax status	Expired at 14 January 2021
Days left	1200 days too late
MOT expiry date	6 March 2021
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4 ARAPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

#### Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

2000000	
**********	
********	
******	
*********	
********	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	







### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2006-01-18
Last registration	2020-02-28
Complete history	See info



Registration #1	2006-01-18	14 mi
Registration #2	2009-03-02	17.766 mi
Registration #3	2010-03-04	23.085 mi
Registration #4	2011-03-04	27.218 mi
Registration #5	2012-03-02	31.271 mi
Registration #6	2013-03-01	35.403 mi
Registration #7	2013-03-02	35.414 mi
Registration #8	2014-03-01	40.402 mi
Registration #9	2015-03-07	45.706 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		10.000 and





### Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Dimensions & weight

Width	1740 mm
Height	1685 mm
Length	4025 mm
Wheel base	2600 mm
Kerb weight	1349 kg
Max. allowed weight	1820 kg

### Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	G4ED5273150