



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	COUPE ATLANTIC
Colour	Silver
Year of manufacture	2006
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	186 Nm at 4.500 rpm
Engine capacity	1.975 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.3 mpg
CO2 emission	193 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-08-02
Pictures	10
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2022-08-02
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	29
Total items failed	2

MOT #16	2021-08-03 15:08
MOT test number	695896631928
Result	✓ Passed
Next expiry date	2022-08-02

MOT #15	2021-03-22 11:43
MOT test number	821863032584
Result	✓ Passed
Advice	Slight blow from centre exhaust
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #14	2020-03-14 09:46
MOT test number	851250495364
Result	✓ Passed
Advice	Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2019-03-09 09:15**MOT test number** 131211263680**Result** ✓ Passed**MOT #12** 2018-03-15 18:54**MOT test number** 770837835666**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #11** 2017-03-18 09:00**MOT test number** 839749729772**Result** ✓ Passed

- Advice** Both side repeaters slightly discolored
- Advice** Exhaust rusty
- Advice** Nearside rear disc in poor condition

**MOT #10** 2016-03-14 08:25**MOT test number** 666087798445**Result** ✓ Passed

- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Exhaust corroded
- Advice** Side repeater slightly discoloured both (1.4.A.2f)

**MOT #9** 2016-03-10 15:19**MOT test number** 798982509506**Result** ✗ Failed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Exhaust corroded**Advice** Side repeater slightly discoloured both (1.4.A.2f)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #8** 2015-03-20 16:46**MOT test number** 848669075098**Result** ✓ Passed**MOT #7** 2014-03-22 10:08**MOT test number** 907151884007**Result** ✓ Passed**MOT #6** 2013-03-09 13:02**MOT test number** 615528163036**Result** ✓ Passed**MOT #5** 2012-03-10 10:22**MOT test number** 797370972030**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #4** 2012-03-10 10:22**MOT test number** 739430372053**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #3** 2011-03-19 12:20**MOT test number** 185198271088**Result** ✓ Passed**MOT #2** 2010-03-13 12:23**MOT test number** 193662270075**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2009-03-02 11:09**MOT test number** 770251569099**Result** ✓ Passed**Notice** Unable to view the front to rear fuel and brake lines fully**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Unable to view the under bonnet fuel and brake lines fully**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Plastic outer sill covers fitted



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2006-03-25
Last registration	2021-08-03
Complete history	<a href="#">See info</a>



Registration #1	2006-03-25	24 mi
Registration #2	2009-03-02	25.155 mi
Registration #3	2010-03-13	28.749 mi
Registration #4	2011-03-19	34.158 mi
Registration #5	2012-03-10	38.118 mi
Registration #6	2013-03-09	43.271 mi
Registration #7	2014-03-22	53.534 mi
Registration #8	2015-03-20	64.670 mi
Registration #9	2016-03-10	73.903 mi
Registration #10	2016-03-20	75.377 mi
Registration #11	2016-03-20	75.377 mi
Registration #12	2016-03-20	75.377 mi
Registration #13	2016-03-20	75.377 mi
Registration #14	2016-03-20	75.377 mi
Registration #15	2016-03-20	75.377 mi
Registration #16	2016-03-20	75.377 mi
Registration #17	2016-03-20	75.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1382 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC6670361