



report date: 2024-03-29

General information

Make	FIAT
Model	IDEA ACTIVE
Colour	Grey
Year of manufacture	2006
Top speed	109 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	128 Nm at 4.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg
CO2 emission	157 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-07-22
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-23
MOT pass rate	63 %
MOT passed	15
Failed MOT tests	9
Total advice items	32
Total items failed	20

MOT #24	2023-08-24 15:26
MOT test number	754535019508
Result	✓ Passed
Next expiry date	2024-08-23
Advice	Rear Coil spring corroded x2 (5.3.1 (b) (i))

MOT #23	2023-08-08 14:08
MOT test number	925212014185
Result	✗ Failed
Advice	Rear Coil spring corroded rear springs corroded (5.3.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner shoulder on limit 185/65/14 (5.2.3 (e))
Fail	Nearside Front Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))
Fail	Nearside Front Lower Suspension component ball joint dust cover no longer prevents the ingress of dirt split (5.3.4 (b) (ii))
Fail	Offside Front Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))
Fail	Nearside Rear Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))

**MOT #22**

2022-08-03 14:08

MOT test number

572104388226

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened x2 (1.1.14 (a) (ii))
- Advice** Rear Brake hose has slight corrosion to ferrule all hoses (1.1.12 (f) (i))
- Advice** Rear Coil spring corroded x2 (5.3.1 (b) (i))
- Advice** Lower Gearbox mounting defective
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing plus wear on inner edge 185/65R14 (5.2.3 (d) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #21**

2022-08-01 16:09

MOT test number

419351154421

Result**✗ Failed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened x2 (1.1.14 (a) (ii))**Fail** Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Brake hose has slight corrosion to ferrule all hoses (1.1.12 (f) (i))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Nearside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))**Advice** Offside Front Tyre slightly damaged/cracking or perishing plus wear on inner edge 185/65R14 (5.2.3 (d) (ii))**Advice** Rear Coil spring corroded x2 (5.3.1 (b) (i))**Advice** Lower Gearbox mounting defective**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**MOT #20**

2021-11-15 15:30

MOT test number

348062318793

Result**✓ Passed****Advice** Rear Coil spring corroded NS/OS (5.3.1 (b) (i))**MOT #19**

2021-11-15 10:54

MOT test number

222879451925

Result**✗ Failed****Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Rear Coil spring corroded NS/OS (5.3.1 (b) (i))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #18** 2020-11-23 12:25**MOT test number** 107408788021**Result** ✓ Passed**Advice** Engine management light on**MOT #17** 2019-11-22 12:05**MOT test number** 778290448140**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases front flexi exhaust (6.1.2 (a))**MOT #16** 2019-11-22 11:26**MOT test number** 623425216489**Result** ✗ Failed**Fail** Nearside Rear Tyre has ply or cords damaged (5.2.3 (d) (ii))**Advice** Front Exhaust has a minor leak of exhaust gases front flexi exhaust (6.1.2 (a))**MOT #15** 2018-11-23 15:54**MOT test number** 948195592291**Result** ✓ Passed**MOT #14** 2018-11-23 12:33**MOT test number** 207591570583**Result** ✗ Failed**Fail** Nearside Front Headlamp aim too low (4.1.2 (a))**Fail** Front Windscreen washer not working (3.5 (a))**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #13** 2017-11-24 10:04**MOT test number** 830352885701**Result** ✓ Passed**MOT #12** 2016-11-14 09:51**MOT test number** 627781217337**Result** ✓ Passed**MOT #11** 2015-10-19 15:43**MOT test number** 464688558174**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2015-10-19 09:15**MOT test number** 317055955011**Result** ✗ Failed**Fail** Nearside Front Macpherson strut insecure (2.4.G.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2014-11-03 12:41**MOT test number** 486097704335**Result** ✓ Passed**MOT #8** 2013-11-07 12:10**MOT test number** 377421113324**Result** ✓ Passed

**MOT #7** 2012-11-02 09:43**MOT test number** 229037902301**Result** ✓ Passed**MOT #6** 2012-11-02 09:43**MOT test number** 999357402329**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #5** 2011-10-10 12:15**MOT test number** 177693381265**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-10-10 12:15**MOT test number** 719863581228**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Rear Direction indicators incorrect colour (1.4.A.2f)**Pass with rectification** Nearside Rear Direction indicators incorrect colour (1.4.A.2f)**MOT #3** 2010-10-25 15:47**MOT test number** 894298590202**Result** ✓ Passed



MOT #2	2010-10-25 09:48
MOT test number	854118390218
Result	✗ Failed
Fail	Offside Registration plate lamp not working (1.1.C.1d)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Offside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #1	2009-11-19 10:46
MOT test number	793403429362
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
23 August 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	23 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-06-30
Last registration	2023-08-24
Complete history	See info



Registration #1	2006-06-30	7 mi
Registration #2	2009-11-19	14.671 mi
Registration #3	2010-10-25	18.292 mi
Registration #4	2010-10-25	18.292 mi
Registration #5	2011-10-10	21.977 mi
Registration #6	2012-11-02	26.586 mi
Registration #7	2013-11-07	49.133 mi
Registration #8	2014-11-03	34.471 mi
Registration #9	2015-10-19	38.272 mi
Registration #10	2015-10-19	38.272 mi
Registration #11	2016-11-14	41.261 mi
Registration #12	2017-11-24	43.093 mi
Registration #13	2018-05-29	43.093 mi
Registration #14	2019-05-29	43.093 mi
Registration #15	2020-05-29	43.093 mi
Registration #16	2021-05-29	43.093 mi
Registration #17	2022-05-29	43.093 mi
Registration #18	2023-05-29	43.093 mi
Registration #19	2023-05-29	43.093 mi
Registration #20	2023-05-29	43.093 mi
Registration #21	2023-05-29	43.093 mi
Registration #22	2023-05-29	43.093 mi
Registration #23	2023-05-29	43.093 mi
Registration #24	2023-05-29	43.093 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1658 mm
Height	1660 mm
Length	3930 mm
Wheel base	2508 mm
Kerb weight	1155 kg
Max. allowed weight	2655 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1055953