



report date: 2024-03-28

General information

Make	KIA
Model	CARENS GS CRDI
Colour	Silver
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	305 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	45.6 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-03
Pictures	19
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #17	2021-09-10 08:08
MOT test number	170197219782
Result	✓ Passed
Next expiry date	2022-09-09

MOT #16	2021-09-08 10:08
MOT test number	466185558055
Result	✗ Failed
Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))	
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #15	2020-10-19 11:27
MOT test number	563108781779
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #14	2019-10-21 11:19
MOT test number	314881278323
Result	✓ Passed
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #13	2019-10-12 13:54
MOT test number	407439460344
Result	✗ Failed
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Fail Offside Headlamp aim too high (4.1.2 (a))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

**MOT #12**

2018-11-02 16:52

MOT test number

151478869311

Result

✓ Passed

- Advice** O/s side repeater is losing its colour.
- Advice** Front and rear no.plates are deteriorating
- Advice** Slight play in n/s front anti roll bar link upper ball joint.

MOT #11

2018-09-28 11:11

MOT test number

573619969939

Result

✗ Failed

- Fail** Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Fail** Offside Front Position lamp not working (4.2.1 (a))

MOT #10

2017-09-26 16:40

MOT test number

891386800209

Result

✓ Passed

- Advice** Offside front tyre wearing on inner edge
- Advice** Nearside Front Upper Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice** Offside front tyre wearing on inner edge
- Advice** Engine management light flashing

**MOT #9** 2017-09-13 09:35**MOT test number** 555633587300**Result** ✗ Failed**Advice** Engine management light flashing**Fail** Central Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' mirror dangles (8.3.1e)**Advice** Offside front tyre wearing on inner edge**Fail** Parking brake lever has no reserve travel (3.1.6b)**Advice** Offside front tyre wearing on inner edge**Advice** Nearside Front Upper Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #8** 2016-09-07 15:57**MOT test number** 971229168360**Result** ✓ Passed**MOT #7** 2016-09-07 09:57**MOT test number** 733413633184**Result** ✗ Failed**Advice** Offside front tyre worn low on inner edge**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt also play in balljoint (2.4.G.2)**Fail** Parking brake lever has no reserve travel (3.1.6b)**MOT #6** 2015-09-18 08:41**MOT test number** 446204794891**Result** ✓ Passed**MOT #5** 2014-09-26 16:50**MOT test number** 897439364245**Result** ✓ Passed

**MOT #4** 2014-09-26 13:09**MOT test number** 159969664283**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3** 2013-09-30 15:29**MOT test number** 695223373264**Result** ✓ Passed**MOT #2** 2012-09-27 12:01**MOT test number** 297781172251**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1 2012-09-26 10:12

MOT test number 848710472232

Result ✗ Failed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Child seat fitted not allowing full inspection of adult belt



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	BN59DCV
Plate since	2019-03-28
Current registration	BN59DCV
Plate since	2019-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-29
Last registration	2021-09-10
Complete history	See info



Registration #1	2009-09-29	21 mi
Registration #2	2012-09-26	24.601 mi
Registration #3	2012-09-27	24.643 mi
Registration #4	2013-09-30	33.559 mi
Registration #5	2014-09-26	41.016 mi
Registration #6	2014-09-26	41.016 mi
Registration #7	2015-09-18	48.647 mi
Registration #8	2016-09-07	54.212 mi
Registration #9	2016-09-07	54.212 mi
Registration #10	2017-09-13	60.560 mi
Registration #11	2018-09-10	66.917 mi
Registration #12	2018-09-10	66.917 mi
Registration #13	2018-09-10	66.917 mi
Registration #14	2018-09-10	66.917 mi
Registration #15	2018-09-10	66.917 mi
Registration #16	2018-09-10	66.917 mi
Registration #17	2018-09-10	66.917 mi
Registration #18	2018-09-10	66.917 mi
Registration #19	2018-09-10	66.917 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1720 mm
Length	4545 mm
Wheel base	2700 mm
Kerb weight	1631 kg
Max. allowed weight	2155 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

D4EA8H382114