



report date: 2024-03-28

General information

Make	VOLVO
Model	C70 C70 LPT CONV GT
Colour	Blue
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	229 Nm at 1.800 rpm
Cylinders	5
Fuel type	Petrol
Consumption city	20.8 mpg
Consumption extra urban	37.2 mpg
Consumption combined	28.8 mpg





MOT history

MOT #20

2022-06-07 09:59

MOT test number

141805872020

Result

✗ Failed

DANGEROUS Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge very low (5.2.3 (e))**MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Front Anti-lock braking system component excessively damaged abs ring (1.6 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**DANGEROUS** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #19

2021-06-02 13:28

MOT test number

404500382930

Result

✓ Passed

MOT #18

2021-06-01 14:47

MOT test number

450589971699

Result

✗ Failed

MAJOR Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #17**

2021-05-05 14:03

MOT test number

948636671383

Result**✗ Failed**

- MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- MAJOR** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- DANGEROUS** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Offside Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))
- DANGEROUS** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #16

2019-07-18 08:50

MOT test number

244598706119

Result**✓ Passed**

- Advice** Nearside Front brake back plate loose
- Advice** Nearside Play in steering rack inner joint(s)
- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Reverse light not working
- Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))

**MOT #15**

2018-04-16 08:18

MOT test number

844599317325

Result

✓ Passed

- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice** Oil leak offside front

MOT #14

2017-04-27 16:21

MOT test number

628524909515

Result

✓ Passed

- Advice** Offside Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
- Advice** Nearside Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

MOT #13

2017-03-29 09:08

MOT test number

731709543593

Result

✗ Failed

- Advice** Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt bottom joints both sides (2.4.G.2)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Front discs pitting inner face also n/s/r disc pitting
- Fail** Offside front brake binding (3.7.B.1)
- Advice** Offside Rear Brake pad(s) wearing thin change soon (3.5.1g)
- Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)

**MOT #12** 2016-03-30 09:11**MOT test number** 459680783859**Result** ✓ Passed**MOT #11** 2016-03-29 11:26**MOT test number** 328586899608**Result** ✗ Failed**Fail** Exhaust system not adequately supported rear bracket broken (7.1.1)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #10** 2015-03-09 11:27**MOT test number** 227588465089**Result** ✓ Passed**MOT #9** 2014-03-10 11:28**MOT test number** 667649164038**Result** ✓ Passed**MOT #8** 2013-03-30 15:52**MOT test number** 928579083054**Result** ✓ Passed**MOT #7** 2013-03-30 08:53**MOT test number** 458789583050**Result** ✗ Failed**Fail** Offside coil spring incomplete (2.4.C.1a)

**MOT #6** 2012-04-05 11:58**MOT test number** 868356092029**Result** ✓ Passed

- Notice** N/s mirror glass missing at time of test
- Advice** Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Wipers split but clearing screen
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2012-04-04 16:26**MOT test number** 387025992005**Result** ✗ Failed

- Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Wipers split but clearing screen
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)
- Pass with rectification** Headlamp aim too low (1.8)
- Advice** Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** N/s mirror glass missing at time of test

**MOT #4**

2011-04-08 13:32

MOT test number

967368591037

Result

✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Front brake discs badly worn & corroded**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3**

2010-03-19 16:57

MOT test number

960118170078

Result

✓ Passed

Notice Off side front - off side rear - near side rear tyres worn to 3mm**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Near side front tyre worn to 2mm**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2**

2009-04-02 14:40

MOT test number

100782899059

Result

✓ Passed

MOT #1

2008-04-04 15:03

MOT test number

761205498039

Result

✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YY05DZC
Plate since	2019-03-28
Current registration	YY05DZC
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-03-30
Last registration	2022-06-07
Complete history	See info



Registration #1	2005-03-30	18 mi
Registration #2	2008-04-04	31.048 mi
Registration #3	2009-04-02	38.823 mi
Registration #4	2010-03-19	48.425 mi
Registration #5	2011-04-08	49.725 mi
Registration #6	2012-04-04	51.009 mi
Registration #7	2012-04-05	51.009 mi
Registration #8	2013-03-30	54.917 mi
Registration #9	2013-03-30	54.917 mi
Registration #10	2014-03-10	57.502 mi
Registration #11	2015-03-09	60.095 mi
Registration #12	2016-03-29	61.377 mi
Registration #13	2016-03-29	61.377 mi
Registration #14	2016-03-29	61.377 mi
Registration #15	2016-03-29	61.377 mi
Registration #16	2016-03-29	61.377 mi
Registration #17	2016-03-29	61.377 mi
Registration #18	2016-03-29	61.377 mi
Registration #19	2016-03-29	61.377 mi
Registration #20	2016-03-29	61.377 mi
Registration #21	2016-03-29	61.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1820 mm
Height	2660 mm
Length	4720 mm
Wheel base	1420 mm
Kerb weight	1565 kg
Max. allowed weight	2010 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	3607172