



report date: 2024-03-28

General information

Make	VAUXHALL
Model	COMBO 1700 CDTI
Colour	Gold
Year of manufacture	-
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	170 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg




LABEL UNKNOWN



Internet history

Entry 4


Date	2023-10-18
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)

Entry 3


Date	2022-10-16
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)

Entry 2

Date	2022-08-23
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-10-06
------	------------

CarCheck.co.uk

page 2/15

Pictures

12

Listing price

[View report](#)



source: cargurus.co.uk

**MOT history**

MOT #17	2022-01-21 08:27
MOT test number	992184718784
Result	✓ Passed
Next expiry date	2023-01-20
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

MOT #16	2021-02-24 12:32
MOT test number	488983211675
Result	✓ Passed
Advice	Oil leak, but not excessive Harsh leak (8.4.1 (a) (i))
Advice	Nearside Front Play in steering rack inner joint(s)
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn Bush (5.1.2 (b) (i))
Advice	Offside Front Play in steering rack inner joint(s) Harsh play
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Minor	Offside Obligatory mirror slightly loose (3.3 (b) (i))
Advice	Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn Bush (5.1.2 (b) (i))
Advice	Warning light on dashboard

**MOT #15**

2021-02-23 15:32

MOT test number

103595260375

Result**✗ Failed**

- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Fail** Nearside Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn Bush (5.1.2 (b) (i))
- Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))
- Fail** Offside Front Headlamp insecure (4.1.1 (c))
- Minor** Offside Obligatory mirror slightly loose (3.3 (b) (i))
- Advice** Warning light on dashboard
- Advice** Offside Front Play in steering rack inner joint(s) Harsh play
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))
- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn Bush (5.1.2 (b) (i))
- Fail** Battery insecure and likely to cause a short circuit (4.13 (a) (ii))
- Fail** Oil leaking excessively from engine (8.4.1 (a) (i))



MOT #14

2020-03-10 15:37

MOT test number

687602793262

Result

✓ Passed

- Minor

Offside Windscreen wiper blade defective (3.4 (b) (i))
- Advice

Vehicles internal headlight adjuster altered to recheck lights
- Advice

Exhaust has a minor leak of exhaust gases rear silencer corroded. (6.1.2 (a))
- Advice

Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Minor

Offside Obligatory mirror slightly loose (3.3 (b) (i))
- Advice

Play in steering rack inner joint(s)
- Advice

Front Brake disc worn, pitted or scored, but not seriously weakened both. (1.1.14 (a) (ii))
- Advice

Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #13**

2020-03-10 12:27

MOT test number

325300815603

Result**✗ Failed**

- Advice** Exhaust has a minor leak of exhaust gases rear silencer corroded. (6.1.2 (a))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both. (1.1.14 (a) (ii))
- Minor** Offside Obligatory mirror slightly loose (3.3 (b) (i))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Play in steering rack inner joint(s)
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))

MOT #12

2019-02-22 12:39

MOT test number

617865721085

Result**✓ Passed**

- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Play in steering rack inner joint(s)

**MOT #11**

2019-02-22 11:19

MOT test number

139651270183

Result

✗ Failed

Advice Offside Play in steering rack inner joint(s)**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #10**

2018-06-12 15:08

MOT test number

465413311376

Result

✓ Passed

Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))**MOT #9**

2018-06-12 10:49

MOT test number

752819366249

Result

✗ Failed

Fail Nearside Direction indicator incorrect colour (4.4.3 (a))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))**Fail** Offside Direction indicator incorrect colour (4.4.3 (a))**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8** 2017-06-13 09:15**MOT test number** 930718848374**Result** ✓ Passed**Advice** Parking brake only just passed**MOT #7** 2016-03-03 12:57**MOT test number** 267961533099**Result** ✓ Passed**Advice** Temp gauge innop**Advice** Offside Front Inner Ball joint has slight play track rod (2.2.B.1f)**Advice** Front windscreen has damage outside swept area**MOT #6** 2015-03-18 11:49**MOT test number** 669197675066**Result** ✓ Passed**MOT #5** 2014-05-07 10:25**MOT test number** 117417024160**Result** ✓ Passed**MOT #4** 2013-04-17 14:47**MOT test number** 576997803134**Result** ✓ Passed**MOT #3** 2013-04-17 12:12**MOT test number** 839777303160**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #2	2012-04-05 13:52
MOT test number	769296192041
Result	✓ Passed

MOT #1	2012-04-05 09:58
MOT test number	107836692491
Result	✗ Failed
<div><div>Fail</div>Rear registration plate incorrect (6.3.1a)</div>	



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 HV09RHU
Plate since	2019-06-29
Current registration	 HV09RHU
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-04-28
Last registration	2022-01-21
Complete history	See info



Registration #1	2009-04-28	14 mi
Registration #2	2012-04-05	14.490 mi
Registration #3	2012-04-05	14.490 mi
Registration #4	2013-04-17	20.243 mi
Registration #5	2013-04-17	20.243 mi
Registration #6	2014-05-07	26.054 mi
Registration #7	2015-03-18	30.157 mi
Registration #8	2016-03-03	64.095 mi
Registration #9	2017-06-13	70.188 mi
Registration #10	2018-06-12	78.376 mi
Registration #11	2018-06-12	78.376 mi
Registration #12	2019-06-20	78.376 mi
Registration #13	2019-06-20	78.376 mi
Registration #14	2019-06-20	78.376 mi
Registration #15	2019-06-20	78.376 mi
Registration #16	2019-06-20	78.376 mi
Registration #17	2019-06-20	78.376 mi
Registration #18	2019-06-20	78.376 mi
Registration #19	2019-06-20	78.376 mi
Registration #20	2019-06-20	78.376 mi
Registration #21	2019-06-20	78.376 mi
Registration #22	2019-06-20	78.376 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1892 mm
Height	1801 mm
Length	4323 mm
Kerb weight	1210 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	2651135