






report date: 2024-03-28

General information

Make	TOYOTA
Model	HILUX 4X4 D-4D D/C INVINCIBLE
Colour	Black
Year of manufacture	2007
Top speed	108 mph
0 - 60 mph	11.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	169 BHP
Max. torque	343 Nm at 1.400 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	23.9 mpg
Consumption extra urban	35.3 mpg
Consumption combined	35.3 mpg



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 2

Date 2021-07-13

Pictures 4

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1


 Date
 2021-07-12

 Pictures
 4

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2024-07-03
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	12
Total items failed	7

MOT #16	2023-07-04 12:22
MOT test number	985463551103
Result	✓ Passed
Next expiry date	2024-07-03
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt Minor Nearside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))	

MOT #15	2023-06-29 11:42	
MOT test number	799566960779	
Result	× Failed	
Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))		
Fail Emissions unable to be completed major leak (8.2.2.2 (e))		
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt		
Fail Central Rear Exhaust has a major leak of exhaust gases rear box with tail pipe broken off from the system (6.1.2 (a))		
Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))		
Minor Nearside Front Steering rack gaiter damaged or deteriorated, but preventing (2.1.3 (g) (i))	the ingress of dirt	

CarCheck.co.uk page 3/13



Result

AE07UCW

report date: 2024-03-28

× Failed

MOT #14 2022-06-27 09:34

MOT test number 817367106711

Result ✓ Passed

Advice Exhaust has a minor leak of exhaust gases from several places - centre section (6.1.2 (a))

MOT #13 2022-06-27 09:34

MOT test number 330402358202

Advice Exhaust has a minor leak of exhaust gases from several places - centre section (6.1.2 (a))

Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #12 2021-02-27 08:06

MOT test number 439126011702

Result ✓ Passed

MOT #11 2020-01-28 07:54

MOT test number 951033444779

Result
✓ Passed

MOT #10 2019-01-31 16:58

MOT test number 367260315742

Result \(\sqrt{Passed} \)

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Front brake pads worn

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #9		2018-01-30 10:47
MOT test	number	489146387044
Result		✓ Passed
Advice	Spare tyre low pressure	
Advice	Nearside front sidelight, bulb? connection?	

MOT #8	2017-01-31 15:01
MOT test number	247057345719
Result	✓ Passed
MOT #7	2016-01-11 09:57
MOT test number	746088760495
Result	✓ Passed
Advice Nearside front wiper blade split	
Advice Nearside front tyre worn very low on inner tread	

MOT #6	2014-12-04 13:00
MOT test number	419138534387
Result	✓ Passed
MOT #5	2013-11-27 11:19
MOT test number	148721633395
Result	✓ Passed
MOT #4	2012-10-08 08:39
MOT test number	319022782491
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #3 2011-03-04 09:23 MOT test number 679263461075

Result

Passed

MOT #2 2011-03-02 09:42

MOT test number 878841961035

Result × Failed

Fail Nearside Track rod end ball joint has excessive play (2.2.B.1f)

MOT #1 2010-03-04 14:11

MOT test number 240303260031

CarCheck.co.uk page 6/13



report date: 2024-03-28

3 July 2024

Tax & MOT check

MOT expiry date



Full MOT history

See MOT history

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	NK NY
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-09
Last registration	2023-07-04
Complete history	See info



Registration #1	2007-03-09	10 mi
Registration #2	2010-03-04	40.934 mi
Registration #3	2011-03-02	48.390 mi
Registration #4	2011-03-04	48.477 mi
Registration #5	2012-10-08	59.370 mi
Registration #6	2013-11-27	60.977 mi
Registration #7	2014-12-04	77.173 mi
Registration #8	2016-01-11	86.994 mi
Registration #9	2017-01-31	97.713 mi
Registration #10	2018-01-30	107.457 mi
Registration #10 Registration #11	2018-01-30	107.457 mi
-		107.457 mi
Registration #11		107.457 mi
Registration #11 Registration #12		107.457 mi
Registration #11 Registration #12 Registration #13		107.457 mi
Registration #11 Registration #12 Registration #13 Registration #14		107.457 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15		107.457 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16		107.457 mi

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1835 mm
Height	1810 mm
Length	5255 mm
Wheel base	3085 mm
Kerb weight	1885 kg
Max. allowed weight	2940 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1KD7231037

CarCheck.co.uk page 13/13