



report date: 2024-03-29

General information

Make	MAZDA
Model	5 FURANO
Colour	Red
Year of manufacture	2010
Top speed	110 mph
0 - 60 mph	13.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	144 BHP
Max. torque	185 Nm at 4.000 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.6 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.8 mpg
CO2 emission	187 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-06-16
Pictures	40
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-06-15
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	23
Total items failed	10

MOT #16	2022-06-16 15:36
MOT test number	286179113972
Result	✓ Passed
Next expiry date	2023-06-15

MOT #15	2021-10-05 16:12
MOT test number	721682248691
Result	✓ Passed

MOT #14	2021-10-04 10:44
MOT test number	606331763401
Result	✗ Failed
Fail	Offside Rear Service brake excessively binding (1.2.1 (f))
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #13	2020-10-23 15:57
MOT test number	248565653750
Result	✓ Passed

**MOT #12** 2020-10-23 10:01**MOT test number** 758530503370**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Nail in tyre**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #11** 2019-10-23 11:28**MOT test number** 848643068951**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #10** 2019-10-23 11:28**MOT test number** 231879088815**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Nail in tyre**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #9** 2018-10-23 15:17**MOT test number** 398126645448**Result** ✓ Passed

**MOT #8** 2018-05-15 10:22**MOT test number** 958321835309**Result** ✓ Passed**Advice** Heat shield insecure**MOT #7** 2018-05-15 10:22**MOT test number** 803982229771**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Heat shield insecure**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #6** 2017-05-03 09:03**MOT test number** 416495943054**Result** ✓ Passed**MOT #5** 2016-05-18 15:12**MOT test number** 720285384797**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Rear n/s and o/s tyres worn on inner tread edges**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #4**

2016-05-18 09:23

MOT test number

937298075956

Result**✗ Failed****Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Rear n/s and o/s tyres worn on inner tread edges**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front tyre WORN on inner tread edge**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #3**

2015-05-26 15:18

MOT test number

419206745190

Result**✓ Passed****Notice** Front o/s tyre cut in tread**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Under-trays fitted obscuring some underside components**MOT #2**

2014-05-19 15:28

MOT test number

257219034474

Result**✓ Passed****Notice** Offside front wiper rubber split but adequately clearing screen.**Notice** Under-trays fitted obscuring some underside components



MOT #1	2013-05-08 13:53
MOT test number	567388223158
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components



Tax & MOT check

✕
Untaxed

Tax expired:
1 January 2023

✕
MOT

Expired:
15 June 2023

Tax status

Expired at 1 January 2023

Days left

483 days too late

MOT expiry date

15 June 2023

Full MOT history

[See MOT history](#)

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	ND10FYJ
Plate since	2019-03-29
Current registration	ND10FYJ
Plate since	2019-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-05-28
Last registration	2022-06-16
Complete history	See info



Registration #1	2010-05-28	11 mi
Registration #2	2013-05-08	21.244 mi
Registration #3	2014-05-19	27.482 mi
Registration #4	2015-05-26	34.805 mi
Registration #5	2016-05-18	41.210 mi
Registration #6	2016-05-18	41.211 mi
Registration #7	2017-05-03	46.042 mi
Registration #8	2018-05-15	50.088 mi
Registration #9	2018-05-15	50.088 mi
Registration #10	2019-05-03	55.000 mi
Registration #11	2019-05-03	55.000 mi
Registration #12	2019-05-03	55.000 mi
Registration #13	2019-05-03	55.000 mi
Registration #14	2019-05-03	55.000 mi
Registration #15	2019-05-03	55.000 mi
Registration #16	2019-05-03	55.000 mi
Registration #17	2019-05-03	55.000 mi
Registration #18	2019-05-03	55.000 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1665 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1410 kg
Max. allowed weight	2125 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Engine number	LF 10895894