

Ford



## General information

I FUSION +
bh
econds
d Manual

## Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	41.5 mpg
CO2 emission	149 g/km
CO2 label	F





## MOT history

MOT expiry date	2023-12-05
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	21
Total items failed	8

MOT #15	2022-12-06 15:27
MOT test number	470330105513
Result	✓ Passed
Next expiry date	2023-12-05

MOT #14		2022-12-06 15:27
MOT test number		810983915237
Result		🗙 Failed
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #13	21	021-11-24 15:52
MOT test	number	554239264954
Result		🗸 Passed
Minor	Front Suspension arm ball joint dust cover severely deteriorated n/s and o/s (5.3.4 (b	o) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a	) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))	
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	





MOT #12		2020-11-09 11:12
MOT test	number	439528761722
Result		Passed
MOT #11		2019-11-06 10:53
MOT test	number	895169215435
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Exhaust has a minor leak of exhaust gases rear box joint (6.1.2 (a))	

MOT #10	2018-11-03 13:13
MOT test number	974406153234
Result	✓ Passed

МОТ #9	2017-11-01 11:04
MOT test number	283222788532
Result	✓ Passed

MOT #8		2016-11-11 14:37
MOT test	number	220234516856
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	



CX09VNC report date: 2024-03-28

MOT #7	2016-11-11 10:46
MOT test number	856807526920
Result	🗙 Failed
Advice Front Brake pad(s) wearing thin (3.5.1g)	
<b>Fail</b> Nearside Rear Tyre has a tear, caused by separation or partial failure of its structu (4.1.D.1b)	re OUTER WALL
Fail Headlamp aim too low BOTH LAMPS (1.8)	
Fail Offside Stop lamp not working INCORRECT BULB (1.2.1b)	
Fail Nearside Rear Valve stem seriously misaligned (4.1.D.1e)	
Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)	

МОТ #6	2015-11-19 11:42
MOT test number	901994817309
Result	✓ Passed

MOT #5		2014-11-27 18:05
MOT test	number	147681734351
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

МОТ #4	2013-11-12 14:34
MOT test number	197236513386
Result	✓ Passed
Notice Nail in offside rear tyre	





MOT #3	2013-11-07 16:27
MOT test number	309131113330
Result	🗙 Failed
Notice Nail in offside rear tyre	
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail Nearside Rear Shock absorber has a serious fluid leak (2.7.3)	
Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
MOT #2	2012-11-06 15:45
MOT test number	916351712346
Result	✓ Passed
Notice High level stop lamp disconnected	
Advice Nearside Front Road wheel slightly damaged (4.2.A.1a)	
Notice Nearside wiper slightly smearing	

**Notice** Nearside front tyre split/perishing

MOT #1	2012-02-23 11:53
MOT test number	675554252016
Result	✓ Passed



Tax & MOT check

✓ Taxed	Х МОТ
Tax due: 1 November 2024	<b>Expired:</b> 5 December 2023
Tax status	Valid until 1 November
Days left	186
MOT expiry date	5 December 2023
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	
************	
********	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Carrent registration Plate since	





#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 



CX09VNC report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-04-07
Last registration	2022-12-06
Complete history	<u>See info</u>



Registration #1	2009-04-07	24 mi
Registration #2	2012-02-23	18.322 mi
Registration #3	2012-11-06	18.654 mi
Registration #4	2013-11-07	23.836 mi
Registration #5	2013-11-12	23.913 mi
Registration #6	2014-11-27	28.119 mi
Registration #7	2015-11-19	32.058 mi
Registration #8	2016-11-11	35.944 mi
Registration #9		11.227 mi
Registration #9 Registration #10		10.000 est
		01.000 est 01.000 est 01.000 est
Registration #10		00.000 est 0.000 est 00.000 est 00.000 est
Registration #10 Registration #11		01.000 est 0.000 est 01.000 est 01.000 est 01.000 est
Registration #10 Registration #11 Registration #12		00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #10 Registration #11 Registration #12 Registration #13		00.000 46 0.000 46 0.000 46 0.000 46 0.000 46 0.000 46 0.000 46

More info >





### Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1952 mm
Height	1534 mm
Length	4020 mm
Wheel base	2485 mm
Kerb weight	1200 kg
Max. allowed weight	1605 kg
Additional information	
Fuel tank capacity	45
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12