



report date: 2024-03-29

General information

Make	KIA
Model	SORENTO CRDI KX-3
Colour	Silver
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	422 Nm at 1.800 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	38.2 mpg
CO2 emission	194 g/km
CO2 label	J





MOT history

MOT expiry date	2024-06-09
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	70
Total items failed	2

MOT #17	2023-06-08 11:53
---------	------------------

MOT test number	313798554876
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-06-09
------------------	------------

- Advice** Seat belt anchorage prescribed area is corroded but not considered excessive offside and nearside sill to floor (7.1.1 (a) (i))
- Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement offside and nearside (d-bush) (5.3.4 (a) (i))
- Advice** Offside Front Brake hose slightly deteriorated corroded (1.1.12 (b) (ii))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear heatshield insecure
- Advice** Rear Brake hose slightly deteriorated offside and nearside corroded (1.1.12 (b) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced offside and nearside (6.1.1 (c) (i))

**MOT #16**

2023-06-05 10:31

MOT test number

416361967915

Result**✗ Failed**

- Advice** Rear Brake hose slightly deteriorated offside and nearside corroded (1.1.12 (b) (ii))
- Advice** Offside Front Brake hose slightly deteriorated corroded (1.1.12 (b) (ii))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Seat belt anchorage prescribed area is corroded but not considered excessive offside and nearside sill to floor (7.1.1 (a) (i))
- MAJOR** Nearside Front Fuel system component leaking fuel filter area (6.1.3 (b) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced offside and nearside (6.1.1 (c) (i))
- Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement offside and nearside (d-bush) (5.3.4 (a) (i))
- MAJOR** Offside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced sill to floor (7.1.1 (a) (i))
- Advice** Offside Rear heatshield insecure

MOT #15

2022-06-10 15:06

MOT test number

300759369064

Result**✓ Passed**

- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material to flexi (1.1.11 (c))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))



MOT #14

2022-06-10 10:49

MOT test number

755168705770

Result

✗ Failed

MAJOR Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt upper boot (5.3.4 (b) (ii))

Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

MAJOR Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt upper boot (5.3.4 (b) (ii))

Advice Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Offside Front Brake pipe corroded, covered in grease or other material to flexi (1.1.11 (c))

MOT #13

2021-05-10 11:15

MOT test number

129130064952

Result

✓ Passed

MOT #12

2021-04-21 09:21

MOT test number

918874273612

Result

✓ Passed

Advice Offside Rear boot heat shield loose and rattling

MOT #11

2021-04-14 12:28

MOT test number

622052437364

Result

✗ Failed

MAJOR Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))

Advice Offside Rear boot heat shield loose and rattling

MAJOR Nearside Rear Rear fog lamp not working (4.5.1 (a) (ii))

MAJOR Nearside Front Suspension arm ball joint excessively worn bottom ball joint has excessive play (5.3.4 (a) (i))

MAJOR Central Rear Trailer electrical socket (13 pin) not operating the trailer lamps as intended (4.10 (c) (i))

**MOT #10**

2019-11-25 08:48

MOT test number

467106336048

Result

✓ Passed

Advice Front Play in steering rack inner joint(s)**Advice** Undertrays fitted**MOT #9**

2019-11-21 12:56

MOT test number

950929262871

Result

✗ Failed

MAJOR Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Undertrays fitted**MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Front Play in steering rack inner joint(s)**MAJOR** Rear Rear fog lamp not working (4.5.1 (a) (ii))**MAJOR** Offside Front Suspension arm pin or bush excessively worn front bush lower arm (5.3.4 (a) (i))**MOT #8**

2018-11-20 15:25

MOT test number

581754630692

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))**Advice** Engine and under covers fitted**Advice** Play in steering rack inner joint(s)

**MOT #7** 2018-11-14 15:48**MOT test number** 995800021206**Result** ✗ Failed

- Advice** Engine and under covers fitted
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Rear fog lamp not working (4.5.1 (a) (ii))
- Advice** Passenger seat(s) missing at time of test
- MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Play in steering rack inner joint(s)
- MAJOR** Nearside Obligatory mirror insecure (3.3 (b) (ii))
- MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #6 2017-11-10 09:01**MOT test number** 390060134521**Result** ✓ Passed

**MOT #5** 2017-11-09 11:11**MOT test number** 401010266745**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Front Windscreen wiper does not clear the windscreen effectively both worn/split (8.2.2)**MOT #4** 2016-11-18 13:15**MOT test number** 168445042103**Result** ✓ Passed**MOT #3** 2015-08-03 16:26**MOT test number** 376175715451**Result** ✓ Passed**MOT #2** 2015-02-03 09:22**MOT test number** 268514835099**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Offside rear tyre starting to wear on inner edge**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Nail in offside rear tyre**MOT #1** 2014-01-29 09:23**MOT test number** 655559524019**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
28 March 2024

✓

MOT

Expires:
9 June 2024

Tax status	Expired at 28 March 2024
Days left	31 days too late
MOT expiry date	9 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-02-10
Last registration	2023-06-08
Complete history	See info



Registration #1	2011-02-10	25 mi
Registration #2	2014-01-29	50.659 mi
Registration #3	2015-02-03	68.275 mi
Registration #4	2015-08-03	73.206 mi
Registration #5	2016-11-18	88.896 mi
Registration #6	2017-11-09	98.953 mi
Registration #7	2017-11-10	98.953 mi
Registration #8	2018-11-14	108.719 mi
Registration #9	2018-11-20	108.721 mi
Registration #10	2019-05-29	121.377 mi
Registration #11	2019-05-29	121.377 mi
Registration #12	2019-05-29	121.377 mi
Registration #13	2019-05-29	121.377 mi
Registration #14	2019-05-29	121.377 mi
Registration #15	2019-05-29	121.377 mi
Registration #16	2019-05-29	121.377 mi
Registration #17	2019-05-29	121.377 mi
Registration #18	2019-05-29	121.377 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	84%
Pedestrian	44%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1885 mm
Height	1755 mm
Length	4685 mm
Wheel base	2700 mm
Kerb weight	1896 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

D4HBBH030559