



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	MATRIX GSI
Colour	Black
Year of manufacture	2007
Top speed	103 mph
0 - 60 mph	14.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	102 BHP
Max. torque	141 Nm at 4.500 rpm
Engine capacity	1.599 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.5 mpg
Consumption extra urban	42.8 mpg
Consumption combined	34.0 mpg
CO2 emission	198 g/km
CO2 label	J





Internet history

Entry 2

Date	2023-03-31
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-15
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-16
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	92
Total items failed	6

MOT #21	2024-04-15 14:15
MOT test number	132427764622
Result	✓ Passed
Next expiry date	2025-04-16
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Minor	Front Windscreen wiper blade defective (3.4 (b) (i))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #20	2023-04-17 18:37
MOT test number	536328647932
Result	✓ Passed

**MOT #19**

2022-06-09 16:37

MOT test number

173250491851

Result

✓ Passed

- Advice** Power steering pipe/hose has slight seepage (2.1.5 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm tread/Worn on edges (5.2.3 (e))
- Advice** Offside Front Suspension arm ball joint has slight play Wishbone (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm ball joint has slight play Wishbone (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm tread/Worn on edges (5.2.3 (e))
- Advice** All direction indicators slightly discoloured (4.4.3 (a))
- Advice** Vehicle heavily corroded underneath
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))



MOT #18

2022-06-08 16:14

MOT test number

476471447132

Result

✗ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2mm tread/Worn on edges (5.2.3 (e))

Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Vehicle heavily corroded underneath

Advice Power steering pipe/hose has slight seepage (2.1.5 (a))

Advice Offside Front Suspension arm ball joint has slight play Wishbone (5.3.4 (a) (i))

MAJOR Offside Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge 2mm tread/Worn on edges (5.2.3 (e))

Advice All direction indicators slightly discoloured (4.4.3 (a))

MAJOR Nearside Front Headlamp aim too low (4.1.2 (a))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))

Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Nearside Front Suspension arm ball joint has slight play Wishbone (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Seat belt buckle missing Rear middle (7.1.2 (d))

MAJOR Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #17**

2021-07-08 16:40

MOT test number

792058137587

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** General under body wear
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #16

2020-08-10 13:53

MOT test number

302933799269

Result

✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** O/s front lower suspension arm rear bush starting to split
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner edge (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #15**

2020-08-07 11:24

MOT test number

206678786635

Result**✗ Failed**

- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** O/s front lower suspension arm rear bush starting to split
- MAJOR** Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner edge (1.1.14 (a) (ii))
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #14

2019-08-14 09:26

MOT test number

487386309813

Result**✓ Passed**

- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated cracking (6.1.7 (g) (i))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated cracking (6.1.7 (g) (i))

**MOT #13**

2019-08-13 11:40

MOT test number

160762421537

Result**✗ Failed****MAJOR** Windscreen washer not working (3.5 (a))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated cracking (6.1.7 (g) (i))**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated cracking (6.1.7 (g) (i))**MOT #12**

2017-11-29 16:48

MOT test number

780461263902

Result**✓ Passed****Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)**Advice** Offside Rear Tyre worn close to the legal limit 195/55/15 (4.1.E.1)**Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)**Advice** Nearside Rear Tyre worn close to the legal limit 195/55/15 (4.1.E.1)**MOT #11**

2017-11-29 11:14

MOT test number

149166399288

Result**✗ Failed****Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)**Advice** Nearside Rear Tyre worn close to the legal limit 195/55/15 (4.1.E.1)**Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Advice** Offside Rear Tyre worn close to the legal limit 195/55/15 (4.1.E.1)

**MOT #10** 2016-11-16 10:52**MOT test number** 757128013442**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases flexible pipe (7.1.2)**MOT #9** 2015-11-26 10:30**MOT test number** 371299559501**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit 195/55/15 (4.1.E.1)**Advice** Nearside Front Drop link dust cover twisted. but still preventing ingress of dirt**Advice** Offside Rear Tyre worn close to the legal limit 195/55/15 (4.1.E.1)**Advice** Offside Rear Nail in tyre**Advice** Offside Front Drop link dust cover twisted. but still preventing ingress of dirt**MOT #8** 2015-11-26 10:30**MOT test number** 580818474100**Result** ✗ Failed**Advice** Offside Rear Nail in tyre**Advice** Offside Front Drop link dust cover twisted. but still preventing ingress of dirt**Pass with rectification** Offside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)**Advice** Offside Rear Tyre worn close to the legal limit 195/55/15 (4.1.E.1)**Advice** Nearside Front Drop link dust cover twisted. but still preventing ingress of dirt**Pass with rectification** Nearside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)**Advice** Nearside Rear Tyre worn close to the legal limit 195/55/15 (4.1.E.1)

**MOT #7** 2014-11-25 13:43**MOT test number** 215039424370**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #6** 2013-11-20 08:37**MOT test number** 128514523340**Result** ✓ Passed**MOT #5** 2013-11-20 08:37**MOT test number** 407514823358**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #4** 2012-11-28 14:49**MOT test number** 577693732348**Result** ✓ Passed**MOT #3** 2011-12-01 10:53**MOT test number** 456055631302**Result** ✓ Passed**Notice** Headlamp masks/converters fitted**MOT #2** 2010-12-01 16:04**MOT test number** 974945730307**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Headlamp masks/converters fitted**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2010-12-01 16:04
MOT test number	431145430313
Result	✗ Failed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)
Notice	Headlamp masks/converters fitted



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
16 April 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	16 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	KR57HVP
Plate since	2019-09-29
Current registration	KR57HVP
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-12-01
Last registration	2024-04-15
Complete history	See info



Registration #1	2007-12-01	11 mi
Registration #2	2010-12-01	29.677 mi
Registration #3	2011-12-01	45.175 mi
Registration #4	2012-11-28	58.583 mi
Registration #5	2013-11-20	68.208 mi
Registration #6	2014-11-25	80.029 mi
Registration #7	2015-11-26	91.081 mi
Registration #8	2015-11-26	91.081 mi
Registration #9	2016-11-16	100.980 mi
Registration #10	2017-11-29	111.549 mi
Registration #11	2017-11-29	111.549 mi
Registration #12	2018-11-29	122.118 mi
Registration #13	2019-11-29	132.687 mi
Registration #14	2020-11-29	143.256 mi
Registration #15	2021-11-29	153.825 mi
Registration #16	2022-11-29	164.394 mi
Registration #17	2023-11-29	174.963 mi
Registration #18	2024-04-15	185.532 mi
Registration #19	2024-04-15	185.532 mi
Registration #20	2024-04-15	185.532 mi
Registration #21	2024-04-15	185.532 mi
Registration #22	2024-04-15	185.532 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1740 mm
Height	1685 mm
Length	4025 mm
Wheel base	2600 mm
Kerb weight	1269 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	G4ED7T007728