



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI S/S
Colour	White
Year of manufacture	2012
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	170 g/km
CO2 label	H








Internet history

Entry 1

Date	2021-03-06
Pictures	22
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-03-15
MOT pass rate	56 %
MOT passed	10
Failed MOT tests	8
Total advice items	40
Total items failed	19

MOT #18	2024-03-04 15:21
MOT test number	979134355325
Result	✓ Passed
Next expiry date	2025-03-15
Advice	Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #17**

2024-03-04 12:30

MOT test number

873094241840

Result**✗ Failed**

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Reversing lamp does not emit a steady white light (4.6.2 (a))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Coolant low
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #16

2023-03-13 15:26

MOT test number

201986785408

Result**✓ Passed**

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Stop lamp(s) light intensity obviously reduced high level (4.3.3 (a) (i))

**MOT #15**

2023-03-13 09:53

MOT test number

715836381354

Result**✗ Failed****Minor** Stop lamp(s) light intensity obviously reduced high level (4.3.3 (a) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Anti-roll bar linkage ball joint likely to become detached (5.3.4 (a) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #14**

2022-03-15 15:59

MOT test number

599557019127

Result**✓ Passed****Advice** Brake pipe corroded, covered in grease or other material all pipes covered grease (1.1.11 (c))**MOT #13**

2022-03-15 14:50

MOT test number

962612684198

Result**✗ Failed****Advice** Brake pipe corroded, covered in grease or other material all pipes covered grease (1.1.11 (c))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #12**

2021-03-16 16:47

MOT test number

372006463919

Result**✓ Passed****Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11** 2020-10-30 17:23**MOT test number** 521715253128**Result** ✓ Passed**MOT #10** 2020-10-30 14:05**MOT test number** 847223747372**Result** ✗ Failed**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**MOT #9** 2019-11-01 16:17**MOT test number** 629501446867**Result** ✓ Passed**Advice** Front Shock absorbers light misting of oil or has limited damping effect both (5.3.2 (b))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**MOT #8** 2019-11-01 11:38**MOT test number** 654704223658**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Rear fog lamp not working (4.5.1 (a) (ii))**Fail** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**Fail** Registration plate does not conform to the specified requirements both front and rear (0.1 (d))**Fail** Rear Stop lamp(s) light intensity significantly reduced center (4.3.3 (a) (ii))**Advice** Front Shock absorbers light misting of oil or has limited damping effect both (5.3.2 (b))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #7**

2018-10-26 15:26

MOT test number

356308127526

Result

✓ Passed

Advice

Central stop lamp dull

MOT #6

2018-10-26 11:22

MOT test number

804628741992

Result

✗ Failed

Fail

Front Registration plate does not conform to the specified requirements (0.1 (d))

Fail

Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Fail

Rear Registration plate does not conform to the specified requirements (0.1 (d))

Advice

Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MOT #5

2017-09-08 12:30

MOT test number

122302579861

Result

✓ Passed

Advice

Nearside Front Shock absorber has a light misting of oil (2.7.3)

Advice

Rear high level brake light not working

MOT #4

2017-09-08 12:30

MOT test number

250718248405

Result

✗ Failed

Advice

Nearside Front Shock absorber has a light misting of oil (2.7.3)

Pass with rectification

Rear registration plate character(s) likely to be misread (6.3.4b)

Advice

Rear high level brake light not working

Pass with rectification

Front registration plate character(s) likely to be misread (6.3.4b)

**MOT #3** 2016-09-03 10:00**MOT test number** 373371946207**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #2** 2015-08-28 15:32**MOT test number** 294715248246**Result** ✓ Passed**Advice** Rear high level brake light not working**MOT #1** 2015-08-28 12:25**MOT test number** 941116059602**Result** ✗ Failed**Advice** Rear high level brake light not working**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Front Headlamp cleaning device inoperative (1.7.2)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
15 March 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	15 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-28
Current registration	*****
Plate since	2024-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2012-08-20
Last registration	2024-03-04
Complete history	See info



Registration #1	2012-08-20	6 mi
Registration #2	2015-08-28	12.549 mi
Registration #3	2015-08-28	12.549 mi
Registration #4	2016-09-03	17.212 mi
Registration #5	2017-09-08	21.796 mi
Registration #6	2017-09-08	21.796 mi
Registration #7	2018-10-26	27.715 mi
Registration #8	2018-10-26	27.718 mi
Registration #9	2019-11-01	37.240 mi
Registration #10	2019-11-01	37.243 mi
Registration #11	2019-11-01	37.243 mi
Registration #12	2019-11-01	37.243 mi
Registration #13	2019-11-01	37.243 mi
Registration #14	2019-11-01	37.243 mi
Registration #15	2019-11-01	37.243 mi
Registration #16	2019-11-01	37.243 mi
Registration #17	2019-11-01	37.243 mi
Registration #18	2019-11-01	37.243 mi
Registration #19	2019-11-01	37.243 mi
Registration #20	2019-11-01	37.243 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	172361K