





report date: 2024-03-29

General information

Make	PEUGEOT
Model	5008 THP ALLURE
Colour	Black
Year of manufacture	2013
Top speed	121 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	156 BHP
Max. torque	240 Nm at 1.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.9 mpg
CO2 emission	163 g/km
CO2 label	G



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-10-07

Pictures 34

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-11-01
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	19
Total items failed	4

MOT #12	2023-11-02 14:01
MOT test number	929835176271
Result	✓ Passed
Next expiry date	2024-11-01

MOT test number

Result

MAJOR Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #10	2022-10-10 13:21
MOT test number	787736645489
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
Advice Nearside Rear Nail in tyre	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #9 2022-10-04 14:00

MOT test number 996153200397

Result X Failed

Advice Nearside Rear Nail in tyre

MAJOR Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

MAJOR Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #8 2021-10-05 11:07

MOT test number 985511196128

Result \(\sqrt{Passed} \)

MOT #7 2020-10-31 10:04

MOT test number 602778444521

Result \(\sqrt{Passed} \)

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2020-10-31 10:04

MOT test number 754868405418

Result X Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #5 2019-05-12 08:13

MOT test number 528825602428

Result ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4 2018-02-28 16:17

MOT test number 464759210253

Result ✓ Passed

MOT #3 2017-07-06 11:09

MOT test number 193794709410

Advice Offside Rear Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #2 2016-07-27 13:33

MOT test number 676149146022

Result
✓ Passed

Advice Offside Rear Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)

Advice Items removed from driver's view prior to test

MOT #1 2016-07-26 13:00

MOT test number 117710006902

Result X Failed

Advice Offside Rear Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)

Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Items removed from driver's view prior to test

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	1 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner	history
OWITE	HISLULY

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	K UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-07-31
Last registration	2023-11-02
Complete history	See info



Registration #1	2013-07-31	9 mi
Registration #2	2016-07-26	21.488 mi
Registration #3	2016-07-27	21.488 mi
Registration #4	2017-07-06	28.734 mi
Registration #5	2018-02-28	32.828 mi
Registration #6	2019-05-12	42.498 mi
Registration #7	2020-10-31	49.749 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	79%
Pedestrian	37%
Safety systems	97%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2118 mm
Height	1638 mm
Length	4530 mm
Wheel base	2728 mm
Kerb weight	1667 kg
Max. allowed weight	2225 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12

Number of axles 2

Engine number FJBS1923748