



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	I40 CRDI ACTIVE BLUE DRIVE
Colour	Black
Year of manufacture	2013
Top speed	124 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	113 g/km
CO2 label	C






Internet history

Entry 2




Date	2021-07-21
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-07-20
Pictures	23
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-02
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	12
Total items failed	5

MOT #13	2023-07-03 09:52
MOT test number	131797870250
Result	✓ Passed
Next expiry date	2024-07-02

MOT #12	2022-06-18 10:51
MOT test number	106664242902
Result	✓ Passed
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11	2022-06-18 10:51
MOT test number	631266336864
Result	✗ Failed
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Pass with rectification	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #10** 2021-07-02 10:45**MOT test number** 750987851224**Result** ✓ Passed**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner and outer shoulder (5.2.3 (e))**MOT #9** 2020-10-15 07:34**MOT test number** 464326540088**Result** ✓ Passed**MOT #8** 2020-09-17 08:36**MOT test number** 489503995066**Result** ✓ Passed**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #7** 2019-08-19 13:46**MOT test number** 707814689736**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #6** 2019-08-19 09:06**MOT test number** 512331713149**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #5** 2018-08-28 14:31**MOT test number** 897590309080**Result** ✓ Passed**MOT #4** 2018-08-28 10:08**MOT test number** 665209564643**Result** ✗ Failed**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #3** 2017-10-06 13:58**MOT test number** 350337726529**Result** ✓ Passed**MOT #2** 2017-10-06 12:55**MOT test number** 799720095996**Result** ✗ Failed**Advice** Nearside Front Brake pad(s) modified but not seriously weakened (3.5.1n)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #1** 2016-09-23 09:20**MOT test number** 476387542961**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
2 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	2 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-09-23
Last registration	2023-07-03
Complete history	See info



Registration #1	2013-09-23	19 mi
Registration #2	2016-09-23	25.503 mi
Registration #3	2017-10-06	37.017 mi
Registration #4	2017-10-06	37.017 mi
Registration #5	2018-08-28	45.877 mi
Registration #6	2018-08-28	45.877 mi
Registration #7	2019-08-19	56.363 mi
Registration #8	2019-08-19	56.363 mi
Registration #9	2019-08-19	56.363 mi
Registration #10	2019-08-19	56.363 mi
Registration #11	2019-08-19	56.363 mi
Registration #12	2019-08-19	56.363 mi
Registration #13	2019-08-19	56.363 mi
Registration #14	2019-08-19	56.363 mi
Registration #15	2019-08-19	56.363 mi
Registration #16	2019-08-19	56.363 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1638 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FDDU318746