



report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 BLUEHDI DSIRE
Colour	Silver
Year of manufacture	2014
Top speed	118 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	285 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	80.7 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	A





Internet history

Entry 1

Date	2022-08-04
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-25
MOT pass rate	54 %
MOT passed	7
Failed MOT tests	6
Total advice items	33
Total items failed	3

MOT #13	2023-07-14 10:59
MOT test number	889431110140
Result	✓ Passed
Next expiry date	2024-07-25

MOT #12	2023-07-14 10:59
MOT test number	706545136317
Result	✗ Failed
Pass with rectification	Tyre has ply or cords exposed both front (5.2.3 (d) (ii))
Pass with rectification	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Pass with rectification	Offside Front Suspension arm insecure and impairing directional stability (5.3.3 (a) (ii))

MOT #11	2022-07-26 14:27
MOT test number	314486071743
Result	✓ Passed

MOT #10	2022-07-26 08:24
MOT test number	113744366625
Result	✗ Failed
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**MOT #9** 2021-08-26 13:12**MOT test number** 169316083513**Result** ✓ Passed**MOT #8** 2021-08-17 11:58**MOT test number** 101559536506**Result** ✗ Failed**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7** 2020-09-18 09:00**MOT test number** 426081077353**Result** ✓ Passed**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Advice** Nearside Front daytime lamp inop

**MOT #6** 2020-09-17 12:16**MOT test number** 344407837011**Result** ✗ Failed**Advice** Nearside Front daytime lamp inop**MAJOR** Offside Rear Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**DANGEROUS** Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Rear Exhaust mounting defective (6.1.2 (a))**MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**MOT #5** 2019-09-11 15:16**MOT test number** 413478361296**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Exhaust mounting defective (6.1.2 (a))

**MOT #4**

2019-09-11 10:13

MOT test number

949654769199

Result**✗ Failed****DANGEROUS** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Rear Exhaust mounting defective (6.1.2 (a))**MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Front Headlamp aim not tested Dip beam not working (4.1.2 (b))**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #3**

2018-08-01 15:54

MOT test number

867393965167

Result**✓ Passed****MOT #2**

2018-07-31 12:43

MOT test number

116348196454

Result**✗ Failed****MAJOR** Nearside Front Windscreen washer not working (3.5 (a))**DANGEROUS** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Front Windscreen washer not working (3.5 (a))**DANGEROUS** Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))



MOT #1	2017-11-07 11:12
MOT test number	976823984110
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
25 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	25 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-11-17
Last registration	2023-07-14
Complete history	See info



Registration #1	2014-11-17	24 mi
Registration #2	2017-11-07	20.242 mi
Registration #3	2018-07-31	26.993 mi
Registration #4	2018-08-01	26.993 mi
Registration #5	2019-09-11	46.242 mi
Registration #6	2019-09-11	46.242 mi
Registration #7	2020-09-17	53.909 mi
Registration #8	2020-09-18	53.918 mi
Registration #9	2020-09-18	53.918 mi
Registration #10	2020-09-18	53.918 mi
Registration #11	2020-09-18	53.918 mi
Registration #12	2020-09-18	53.918 mi
Registration #13	2020-09-18	53.918 mi
Registration #14	2020-09-18	53.918 mi
Registration #15	2020-09-18	53.918 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1090 kg
Max. allowed weight	1598 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBGX3003641