





report date: 2024-03-28

#### General information

Make	CITROEN
Model	C4 CACTUS PURETECH FLAIR S/S
Colour	Grey
Year of manufacture	2016
Top speed	117 mph
0 - 60 mph	9.3 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	109 BHP
Max. torque	205 Nm at 1.500 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	52.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg
CO2 emission	100 g/km
CO2 label	Α



CarCheck.co.uk page 1/12



report date: 2024-03-28

## Internet history

#### Entry 2


Date	2022-02-28
Pictures	0
Listing price	<u>View report</u>

#### source: cargurus.co.uk

#### Entry 1

Date	2021-09-28	
Pictures	11	
Listing price	View report	









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2025-01-05
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	20
Total items failed	18

MOT #8	2024-01-03 12:48
MOT test number	284681376069
Result	✓ Passed
Next expiry date	2025-01-05
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #7		2023-01-06 16:13
MOT test	number	176362667475
Result		✓ Passed
<b>Advice</b> requires a	Rear Brakes imbalanced requirements only just met. It would appear that the $k$ djustment or repair. (1.2.1 (b) (i))	oraking system
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive	movement (5.3.4
Advice	Offside headlamp unit loose and beam image slightly incorrect	
Advice	Items removed from driver's view prior to test	

MOT #6	2021-12-21 15:30
MOT test number	536506458747
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



(i))

**EA66GMY** 

report date: 2024-03-28

MOT test number

565267630332

Result

Advice
(a) (i))

Advice

Driver's view Items removed from driver's view prior to test permit moved (3.1 (a) (ii))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

**MOT #4** 2021-01-04 12:10 **MOT** test number 150374767792 Result × Failed Offside Front Brake hose excessively twisted rubbing on hub (1.1.12 (b) (ii)) Fail Fail Offside Front Tyre tread depth below requirements of 1.6mm 0mm (5.2.3 (e)) Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail **Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Fail Offside Headlamp insecure crash damage (4.1.1 (c)) Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) Nearside Tyre tread depth below requirements of 1.6mm 0mm (5.2.3 (e)) Fail Fail Rear Seat belt anchorage loose centre, bolt missing (7.1.1 (b)) **Advice** Driver's view Items removed from driver's view prior to test permit moved (3.1 (a) (ii)) Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) **Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii)) Offside Stop lamp(s) not working (4.3.1 (a) (ii)) Fail

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #3

MOT test number

426938848699

Result

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #2** 2019-11-05 11:37 **MOT** test number 139950764914 Result × Failed Fail Emissions not tested Engine does not have sufficient engine oil for the test. (8.2.1.2 (d)) Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) **Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) Fail (ii)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #1** 2019-10-21 11:03 **MOT** test number 432415967573 Result × Failed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) Fail Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 5/12



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	5 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

$\sim$		
Owner	hictory	7
OWITCE	1113601	1

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here.  More info >  Plate changes  See in this check if this CITROEN had different number plates.  More info >		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.	*********	
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.	***************************************	
See in this check if this CITROEN had different number plates.		More info >
器 UK  UK	Plate changes	
THE REPORT OF THE PROPERTY OF	See in this check if this CITROEN had different number plates.	
THE REPORT OF THE PROPERTY OF	Number of plates	,
Plate since	Current registration	OK SIE
Plate since	Plate since	
More info >	Current registration	NK SIN
More info >	Plate since	
		More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-11-09
Last registration	2024-01-03
Complete history	See info



Registration #1	2016-11-09	22 mi
Registration #2	2019-10-21	34.911 mi
Registration #3	2019-11-05	35.292 mi
Registration #4	2019-11-07	35.377 mi
Registration #5	2021-01-04	47.979 mi
Registration #6	2021-01-06	47.981 mi
Registration #7		11.777 es
Registration #8		11.117 es
Registration #9		11.177 mi
Registration #10		11.777 es
Registration #11		9.777 sc

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

## Safety ratings

NCAP rating	****
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



## Dimensions & weight

Width	1729 mm
Height	1480 mm
Length	4157 mm
Wheel base	2595 mm
Kerb weight	1020 kg
Max. allowed weight	1555 kg

## Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	XV120205743

CarCheck.co.uk page 12/12