




report date: 2024-03-29

General information

Make	KIA
Model	SORENTO CRDI KX-3
Colour	Black
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	422 Nm at 1.800 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	38.2 mpg
CO2 emission	194 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-08-27
Pictures	2
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-11
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	18
Total items failed	9

MOT #13	2023-10-12 13:02
MOT test number	587777954834
Result	✓ Passed
Next expiry date	2024-10-11
Advice	Offside Front Tyre worn close to legal limit/worn on edge slightly worn on inner edge (5.2.3 (e))

MOT #12	2022-10-07 14:51
MOT test number	946287355386
Result	✓ Passed

MOT #11	2022-10-06 14:10
MOT test number	979818634397
Result	✗ Failed
Fail	Nearside Rear Parking brake inoperative on one side low effort (1.4.1 (a))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Offside Front Lower Suspension arm ball joint excessively worn lower joint has excessive play (5.3.4 (a) (i))

**MOT #10**

2021-10-12 11:20

MOT test number

133119620343

Result

✓ Passed

Minor Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**Minor** Offside Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))**MOT #9**

2021-10-12 11:20

MOT test number

696378784556

Result

✗ Failed

Minor Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Offside Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))**MOT #8**

2020-10-05 13:53

MOT test number

354056968237

Result

✓ Passed

Advice Rear Coil spring corroded both (5.3.1 (b) (i))**Advice** Parking brake requirements only just met due to non usage customer advised**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement split and perished (5.3.4 (a) (i))**Advice** Nearside Front fog lamp damaged and insecure**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement split and perished (5.3.4 (a) (i))

**MOT #7** 2020-09-28 12:05**MOT test number** 624119048571**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement split and perished (5.3.4 (a) (i))**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**Fail** Offside Front Upper Shock absorbers likely to become detached top mount badly worn (5.3.2 (a) (ii))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement split and perished (5.3.4 (a) (i))**Fail** Nearside Front Upper Shock absorbers likely to become detached top mounting badly worn (5.3.2 (a) (ii))**Advice** Nearside Front fog lamp damaged and insecure**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**MOT #6** 2019-03-06 10:40**MOT test number** 461189059652**Result** ✓ Passed**MOT #5** 2017-10-28 08:49**MOT test number** 980943082856**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #4	2016-11-21 09:46
--------	------------------

MOT test number	464724624416
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #3	2016-01-22 15:36
--------	------------------

MOT test number	965867461956
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #2	2014-11-27 14:51
--------	------------------

MOT test number	987221434336
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #1	2013-12-04 09:38
--------	------------------

MOT test number	935710743304
-----------------	--------------

Result	✓ Passed
--------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
11 October 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	11 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-12-03
Last registration	2023-10-12
Complete history	See info



Registration #1	2010-12-03	15 mi
Registration #2	2013-12-04	32.271 mi
Registration #3	2014-11-27	44.213 mi
Registration #4	2016-01-22	66.205 mi
Registration #5	2016-11-21	66.572 mi
Registration #6	2017-10-28	73.845 mi
Registration #7	2019-03-06	81.154 mi
Registration #8	2020-09-28	90.951 mi
Registration #9	2022-05-20	100.748 mi
Registration #10	2022-05-20	100.748 mi
Registration #11	2022-05-20	100.748 mi
Registration #12	2022-05-20	100.748 mi
Registration #13	2022-05-20	100.748 mi
Registration #14	2022-05-20	100.748 mi
Registration #15	2022-05-20	100.748 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	84%
Pedestrian	44%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1885 mm
Height	1755 mm
Length	4685 mm
Wheel base	2700 mm
Kerb weight	1896 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number	D4HBAH003807
---------------	--------------