





report date: 2024-03-28

General information

Make	HYUNDAI
Model	I30 T-GDI S
Colour	Black
Year of manufacture	2018
Top speed	118 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP	
Max. torque	171 Nm at 4.000 rpm	
Engine capacity	998 cc	
Cylinders	3	
Fuel type	Petrol	
Consumption city	50.4 mpg	
Consumption extra urban	64.2 mpg	
Consumption combined	57.7 mpg	
CO2 emission	112 g/km	
CO2 label	С	



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

 Date
 2022-08-10

 Pictures
 4

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT expiry date	2025-04-18
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	7
Total items failed	2

MOT #5		2024-03-21 08:43
MOT test	number	651757551143
Result		✓ Passed
Next expiry date 2025-04-1		2025-04-18
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Advice Front Brake disc worn, pitted or scored, but not seriously weakened lipped (1.1.14 (a) (ii))		

MOT #4		2023-03-28 07:50
MOT test	number	599807682323
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing tyre trea	ad cracking (5.2.3 (d) (ii))

MOT #3		2022-04-19 12:24
MOT test	number	404276407060
Result		✓ Passed
Advice Advice	Brake disc worn, pitted or scored, but not seriously weakened all 4 (1.1.14 (a) (ii) Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #2 2022-04-19 10:33

MOT test number 281042070891

Result X Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Brake disc worn, pitted or scored, but not seriously weakened all 4 (1.1.14 (a) (ii))

MOT #1 2021-02-17 09:08

MOT test number 416268465811

Result ✓ Passed

CarCheck.co.uk page 4/11



DY18FDP report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	18 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

·	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	AR ARE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combont info	

Contact info

More info >

CarCheck.co.uk page 9/11



DY18FDP report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-03-31
Last registration	2024-03-21
Complete history	See info



Registration #1	2018-03-31	12 mi
Registration #2	2021-02-17	23.426 mi
Registration #3	2022-04-19	34.484 mi
Registration #4	2022-04-19	34.484 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		0.0746

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	88%
Children	84%
Pedestrian	64%
Safety systems	68%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1455 mm
Length	4340 mm
Wheel base	2650 mm
Kerb weight	1342 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/3

Number of axles 2

Engine number G3LCHP028584