



RENAULT



SGIOCZE


report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE VVT
Colour	Grey
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	151 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.8 mpg
CO2 emission	162 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2024-10-02
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	26
Total items failed	2

MOT #18	2023-09-19 14:50
MOT test number	730996958745
Result	✓ Passed
Next expiry date	2024-10-02
<b>Advice</b>	Rear Shock absorbers has slight external damage to the casing Advise both rear lower casing corroded (5.3.2 (b))
<b>Minor</b>	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #17	2023-09-19 12:01
MOT test number	276288965476
Result	✗ Failed
<b>MAJOR</b>	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
<b>Minor</b>	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>MAJOR</b>	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
<b>Advice</b>	Rear Shock absorbers has slight external damage to the casing Advise both rear lower casing corroded (5.3.2 (b))

MOT #16	2022-09-28 15:59
MOT test number	745061903267
Result	✓ Passed
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**MOT #15** 2022-09-28 10:10**MOT test number** 880655057684**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Front Position lamp adversely affected by the operation of another lamp Both front lamp faulty (4.2.3 (c))**Advice** Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**MOT #14** 2021-09-28 13:46**MOT test number** 654382565055**Result** ✓ Passed**MOT #13** 2020-09-29 09:08**MOT test number** 481410012702**Result** ✓ Passed**Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #12** 2020-09-28 08:13**MOT test number** 169315565681**Result** ✗ Failed**Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))**MAJOR** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #11** 2019-09-26 15:43**MOT test number** 517286133329**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10** 2019-09-26 08:10**MOT test number** 994506476677**Result** ✗ Failed**MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #9** 2018-10-03 09:45**MOT test number** 344751431758**Result** ✓ Passed**MOT #8** 2017-09-28 09:25**MOT test number** 522938721249**Result** ✓ Passed**Advice** Nearside Front Macpherson strut corroded but not seriously weakened (2.4.G.1)**Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2016-09-09 11:50**MOT test number** 864088857837**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #6** 2016-09-09 11:50**MOT test number** 650441745341**Result** ✗ Failed**Pass with rectification** Offside Outer Front constant velocity joint is insecure (2.5.C.1b)**Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #5** 2015-09-21 09:04**MOT test number** 939716533026**Result** ✓ Passed**MOT #4** 2015-09-21 09:04**MOT test number** 338181267896**Result** ✗ Failed**Pass with rectification** Offside Front Outer Front constant velocity joint is insecure (2.5.C.1b)**MOT #3** 2014-09-25 12:09**MOT test number** 856108964214**Result** ✓ Passed**MOT #2** 2013-09-28 09:15**MOT test number** 559031573257**Result** ✓ Passed**MOT #1** 2013-01-30 15:38**MOT test number** 235890633089**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
2 October 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	2 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>SG10CZE</b>
Plate since	2019-09-29
Current registration	<b>SG10CZE</b>
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	2024-03-29
Agreement type	RENT TO BUY
Agreement term	36 months
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-03-12
Last registration	2023-09-19
Complete history	<a href="#">See info</a>



Registration #1	2010-03-12	28 mi
Registration #2	2013-01-30	26.678 mi
Registration #3	2013-09-28	34.101 mi
Registration #4	2014-09-25	42.330 mi
Registration #5	2015-09-21	47.359 mi
Registration #6	2015-09-21	47.359 mi
Registration #7	2016-09-09	53.242 mi
Registration #8	2016-09-09	53.242 mi
Registration #9	2017-09-28	60.550 mi
Registration #10	2018-10-03	66.828 mi
Registration #11	2019-09-28	73.106 mi
Registration #12	2020-09-28	79.384 mi
Registration #13	2021-09-28	85.662 mi
Registration #14	2022-09-28	91.940 mi
Registration #15	2023-09-19	98.218 mi
Registration #16	2023-09-19	98.218 mi
Registration #17	2023-09-19	98.218 mi
Registration #18	2023-09-19	98.218 mi
Registration #19	2023-09-19	98.218 mi
Registration #20	2023-09-19	98.218 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2037 mm
Height	1423 mm
Length	4299 mm
Wheel base	2640 mm
Kerb weight	1205 kg
Max. allowed weight	1728 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Engine number	D051208
---------------	---------