



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA DESIRE 16V PICASSO E4
Colour	Beige
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg






Internet history

Entry 1

Date	2022-07-20
Pictures	12
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #20	2022-12-06 10:55
MOT test number	328893747605
Result	✓ Passed
Next expiry date	2023-12-09
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #19	2022-12-06 10:54
MOT test number	330973852525
Result	✗ Failed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Pass with rectification	Windscreen washer not working (3.5 (a))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #18	2021-11-27 09:32
MOT test number	326251867309
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #17	2020-11-21 09:37
MOT test number	591049123693
Result	✓ Passed
Advice	Front Tyre slightly damaged/cracking or perishing Both sides (5.2.3 (d) (ii))
Advice	Nearside Rear Exhaust silencer slightly loose Bracket broken due to excessive corrosion. (8.1.1 (b) (i))
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords Outer side wall (5.2.3 (d) (i))

**MOT #16** 2019-11-13 11:41**MOT test number** 902147814396**Result** ✓ Passed**Advice** Exhaust mounting defective rear band snapped (6.1.2 (a))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #15** 2018-11-13 10:26**MOT test number** 391181479702**Result** ✓ Passed**MOT #14** 2017-11-26 13:04**MOT test number** 645189830529**Result** ✓ Passed**MOT #13** 2016-12-01 10:20**MOT test number** 159700416467**Result** ✓ Passed**Advice** Nearside Front Steering rack gaiter deteriorated (2.2.D.2d)**MOT #12** 2015-12-01 14:22**MOT test number** 768771776336**Result** ✓ Passed**MOT #11** 2015-12-01 10:54**MOT test number** 631181280129**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)

**MOT #10** 2014-11-18 09:15**MOT test number** 626632424393**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #9** 2014-11-18 09:15**MOT test number** 556252924356**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #8** 2013-11-20 16:30**MOT test number** 466514123411**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #7** 2013-11-20 10:35**MOT test number** 839844723389**Result** ✗ Failed**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #6** 2012-11-15 14:37**MOT test number** 826690022380**Result** ✓ Passed

**MOT #5** 2012-11-14 16:01**MOT test number** 477339612471**Result** ✗ Failed

Fail Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #4 2011-11-24 10:33**MOT test number** 347378221344**Result** ✓ Passed**MOT #3** 2010-11-17 11:37**MOT test number** 134401420304**Result** ✓ Passed

Notice Child seat fitted not allowing full inspection of adult belt

MOT #2 2009-11-18 15:53**MOT test number** 142942529341**Result** ✓ Passed**MOT #1** 2008-11-21 12:21**MOT test number** 173406528350**Result** ✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-12-09
Last registration	2022-12-06
Complete history	See info



Registration #1	2005-12-09	25 mi
Registration #2	2008-11-21	18.576 mi
Registration #3	2009-11-18	22.987 mi
Registration #4	2010-11-17	26.721 mi
Registration #5	2011-11-24	31.524 mi
Registration #6	2012-11-14	35.217 mi
Registration #7	2012-11-15	35.219 mi
Registration #8	2013-11-20	39.543 mi
Registration #9	2013-11-20	39.543 mi
Registration #10	2014-11-18	44.929 mi
Registration #11	2015-12-01	50.012 mi
Registration #12	2016-12-01	55.000 mi
Registration #13	2017-12-01	60.000 mi
Registration #14	2018-12-01	65.000 mi
Registration #15	2019-12-01	70.000 mi
Registration #16	2020-12-01	75.000 mi
Registration #17	2021-12-01	80.000 mi
Registration #18	2022-12-06	85.000 mi
Registration #19	2022-12-06	85.000 mi
Registration #20	2022-12-06	85.000 mi
Registration #21	2022-12-06	85.000 mi

More info >



Safety ratings

NCAP rating

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX6P2750542