





report date: 2024-03-28

## General information

Make	HYUNDAI
Model	130 CRDI ACTIVE BLUE DRIVE
Colour	Silver
Year of manufacture	2013
Top speed	115 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	108 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	68.9 mpg
Consumption extra urban	80.7 mpg
Consumption combined	76.3 mpg
CO2 emission	97 g/km
CO2 label	Α



CarCheck.co.uk page 1/12



## Internet history

Entry	1

LIICI Y I	
Date	2021-01-31
Pictures	0
Listing price	View report

source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-03-24
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	5
Total items failed	5

MOT #10		2024-03-21 12:02
MOT test	number	367558062422
Result		✓ Passed
Next expi	ry date	2025-03-24
Advice	Rear Tyre worn close to legal limit/worn on edge 195-65-15 (5.2.3 (e))	
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))		
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #9	2023-03-14 14:33
MOT test number	239656241381
Result	<b>✓</b> Passed
MOT #8	2022-03-23 13:59
MOT test number	903069548015
Result	<b>✓</b> Passed
MOT #7	2021-03-25 12:16
MOT test number	804810070156
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



EA13CHX

report date: 2024-03-28

MOT #	6	2021-03-22 12:21
MOT te	est number	850667890759
Result		<b>×</b> Failed
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))	
Fail	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))	
Fail	Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail (d))	Offside Rear Parking brake lever defective so that it cannot be satisfactorily operate	ted caliper (1.1.6

MOT #5	2020-03-10 14:58
MOT test number	312742431577
Result	✓ Passed
MOT #4	2019-03-19 15:37
MOT test number	969113283273
Result	✓ Passed
MOT #3	2018-03-05 15:44
MOT test number	653259186724
Result	<b>✓</b> Passed
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #2	2017-03-21 12:14
MOT test number	800207236275
Result	<b>✓</b> Passed
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 4/12



MOT #1 2016-03-21 11:27

**MOT test number** 715088398698

CarCheck.co.uk page 5/12



#### Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	24 March 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when mistery		
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		DAI
********		
***************************************		
***************************************		
	More info	<b>&gt;</b>
Plate changes		
See in this check if this HYUNDAI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	<b>&gt;</b>

CarCheck.co.uk page 9/12



#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



EA13CHX

report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-05-08
Last registration	2024-03-21
Complete history	See info



Registration #1	2013-05-08	9 mi
Registration #2	2016-03-21	28.939 mi
Registration #3	2017-03-21	34.164 mi
Registration #4	2018-03-05	37.964 mi
Registration #5	2019-03-19	41.792 mi
Registration #6	2020-03-10	43.763 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	90%
Children	90%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



## Dimensions & weight

Width	1780 mm
Height	1500 mm
Length	4485 mm
Wheel base	2650 mm
Kerb weight	1360 kg
Max. allowed weight	1810 kg

# Additional information

Fuel tank capacity	53 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12