



**YB06TXX**

report date: 2024-03-29

General information

Make	FORD
Model	RANGER XLT 4X4 TD
Colour	White
Year of manufacture	2006
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	266 Nm at 2.000 rpm
Engine capacity	2.500 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-05-21
Pictures	14
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2022-07-08
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	40
Total items failed	5

MOT #16	2021-07-09 13:49
MOT test number	158654706233
Result	✓ Passed
Next expiry date	2022-07-08
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #15	2021-07-09 10:04
MOT test number	146934094734
Result	✗ Failed
Fail	Offside Front Brake pipe connection leaking on an air braking system (1.1.11 (b) (i))
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Fail	Offside Front Brake pipe excessively corroded (1.1.11 (c))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #14**

2020-09-17 13:48

**MOT test number**

653730978347

**Result**

✓ Passed

**Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Both front brake pipes showing signs of corrosion

**Advice** Brake disc worn, but not excessively Both fronts (1.1.14 (a) (i))

**Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #13**

2019-05-09 08:51

**MOT test number**

153958170003

**Result**

✓ Passed

**Advice** Vehicle structure showing signs of corrosion

**Advice** Both inner and outer sills showing signs of corrosion

**Advice** Vehicle chassis showing signs of corrosion

**Advice** All suspension components showing signs of corrosion

**Advice** Brake load sensing valve damp

**Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))

**MOT #12**

2018-05-17 09:45

**MOT test number**

620143527659

**Result**

✓ Passed

**Advice** All metal brake pipes coated in grease

**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #11**

2017-05-17 09:36

**MOT test number**

122132423774

**Result**

✓ Passed

**Advice** Nearside Front Inner Tyre worn close to the legal limit edge worn (4.1.E.1)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Rear brake pipes greased making inspection difficult**Advice** Offside Rear Inner Tyre worn close to the legal limit edge worn (4.1.E.1)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #10**

2016-05-20 12:19

**MOT test number**

609655474518

**Result**

✓ Passed

**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** All metal brake pipes coated in grease making inspection difficult**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Various chips across windscreen**MOT #9**

2016-05-20 09:05

**MOT test number**

845685089056

**Result**

✗ Failed

**Advice** All metal brake pipes coated in grease making inspection difficult**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Various chips across windscreen**Fail** Exhaust emits excessive smoke or vapour of any colour (7.4.B.4)

**MOT #8** 2015-05-22 10:33**MOT test number** 358402545190**Result** ✓ Passed

- Notice** Various chips across windscreen
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Notice** Front to rear brake pipes coated in grease making inspection difficult

**MOT #7** 2014-05-19 10:40**MOT test number** 906309734182**Result** ✓ Passed

- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Notice** Rear exhaust bracket insecure
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)

**MOT #6** 2013-05-29 11:57**MOT test number** 735759043108**Result** ✓ Passed**MOT #5** 2012-06-15 11:49**MOT test number** 616947262133**Result** ✓ Passed**MOT #4** 2011-05-25 09:00**MOT test number** 617575441169**Result** ✓ Passed



MOT #3	2011-05-24 12:49
MOT test number	165574141110
Result	✗ Failed
<div>Fail</div> Brakes imbalanced across an axle (3.7.B.5b)	

MOT #2	2010-06-16 12:00
MOT test number	651657760151
Result	✓ Passed

MOT #1	2009-06-22 09:40
MOT test number	592133979190
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	YB06TXX
Plate since	2019-09-29
Current registration	YB06TXX
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-07-20
Last registration	2021-07-09
Complete history	<a href="#">See info</a>



Registration #1	2006-07-20	12 mi
Registration #2	2009-06-22	47.298 mi
Registration #3	2010-06-16	65.908 mi
Registration #4	2011-05-24	79.719 mi
Registration #5	2011-05-25	79.780 mi
Registration #6	2012-06-15	92.480 mi
Registration #7	2013-05-29	98.743 mi
Registration #8	2014-05-19	100.670 mi
Registration #9	2015-05-22	101.900 mi
Registration #10	2016-05-22	101.900 mi
Registration #11	2016-05-22	101.900 mi
Registration #12	2016-05-22	101.900 mi
Registration #13	2016-05-22	101.900 mi
Registration #14	2016-05-22	101.900 mi
Registration #15	2016-05-22	101.900 mi
Registration #16	2016-05-22	101.900 mi
Registration #17	2016-05-22	101.900 mi
Registration #18	2016-05-22	101.900 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	70 l
Fuel delivery	Indirect Injection
Number of doors	4
Number of seats	5
Engine number	588234