





report date: 2024-03-29

### General information

Make	FORD
Model	KUGA ST-LINE TDCI
Colour	Grey
Year of manufacture	2017
Top speed	124 mph
0 - 100 km/h	9.2 seconds
0 - 60 mph	10.0 seconds
Gearbox	6 speed automatic

### Engine & fuel consumption

Power	110 kW / 150 HP / 178 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	57.6 mpg
Consumption combined	54.3 mpg
CO2 emission	134 g/km
CO2 label	Е



CarCheck.co.uk page 1/11



## Internet history

### Entry 2

Date 2021-12-03


Pictures 41

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-12-03
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

## MOT history

MOT expiry date	2025-03-01
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	8
Total items failed	7

MOT #5		2024-03-01 16:11
MOT test i	number	892665106162
Result		✓ Passed
Next expir	y date	2025-03-01
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Rear Nail in tyre	

MOT #4	2024-02-29 09:49
MOT test number	549111302729
Result	<b>X</b> Failed
Fail Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer pro (5.3.4 (b) (ii))	events the ingress of dirt
Advice Nearside Rear Nail in tyre	
Fail Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prev (5.3.4 (b) (ii))	vents the ingress of dirt
Fail Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))	
<b>Fail</b> Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer pro (5.3.4 (b) (ii))	events the ingress of dirt
<b>Fail</b> Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prev (5.3.4 (b) (ii))	vents the ingress of dirt
Fail Offside Front Lower Anti-roll bar linkage ball joint excessively worn (5.3.4 (a	a) (i))
Fail Emissions unable to be completed Due to leak (8.2.2.2 (e))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #3

MOT test number

936062598895

Result

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Front Inner Tyre worn close to legal limit/worn on edge Edge)(Both sides (5.2.3 (e))

MOT #2 2022-03-02 08:15 **MOT** test number 278308901631 Result ✓ Passed MOT #1 2020-12-23 14:49 130564044016 **MOT test number** ✓ Passed Result **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice Under Tray Fitted** 

CarCheck.co.uk page 4/11



# Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	1 March 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	Н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this FORD? How many owners check it in the premium report and see all owner registrations. Download the full report	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	NK NK
Plate since	
	More info

CarCheck.co.uk page 8/11



#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-12-29
Last registration	2024-03-01
Complete history	See info



Registration #1	2017-12-29	25 mi
Registration #2	2020-12-23	59.463 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71,777 es

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	94%
Children	86%
Pedestrian	70%
Safety systems	100%
Overall rating	88%
Video	see crash video



# Dimensions & weight

Width	2086 mm
Height	1737 mm
Length	4541 mm
Wheel base	2690 mm
Kerb weight	1616 kg
Max. allowed weight	2230 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of axles CarCheck.co.uk	2 page 11/1