



report date: 2024-03-28

General information

Make	FIAT
Model	BRAVO ACTIVE TJET
Colour	Blue
Year of manufacture	2010
Top speed	122 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	206 Nm at 1.750 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-01-21
Pictures	34
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-22
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	37
Total items failed	20

MOT #15	2023-06-23 12:33
MOT test number	179624090550
Result	✓ Passed
Next expiry date	2024-06-22

MOT #14	2023-01-20 17:05
MOT test number	545843072136
Result	✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #13**

2023-01-20 15:03

MOT test number

410120709132

Result**✗ Failed**

- Fail** Emissions not tested (8.2.2.2 (e))
- Advice** Rear Child Seat fitted not allowing full inspection of adult belt
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Exhaust emissions likely to be affected by an exhaust leak (8.2.2.1 (b))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))

MOT #12

2022-01-19 14:37

MOT test number

442705877143

Result**✓ Passed****MOT #11**

2021-01-22 09:15

MOT test number

105687807918

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Oil leak, but not excessive drive shaft seal (8.4.1 (a) (i))

**MOT #10**

2021-01-20 11:23

MOT test number

652261736466

Result**✗ Failed****Advice** Nearside Front Oil leak, but not excessive drive shaft seal (8.4.1 (a) (i))**Fail** Brake lever has insufficient reserve travel (1.1.2 (a))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Advice** Coolant low**Fail** Driver's view of the road through the swept area of the windscreen materially affected by an obstruction (3.1 (a) (ii))**Fail** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Windscreen washer not working (3.5 (a))**MOT #9**

2019-07-03 17:48

MOT test number

657361262798

Result**✓ Passed****Advice** Brake pipe corroded, covered in grease or other material front to rear slightly swollen beneath paint (1.1.11 (c))**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material slightly swollen beneath paint (1.1.11 (c))

**MOT #8**

2019-07-02 12:54

MOT test number

719522944845

Result**✗ Failed**

Advice Nearside Front Brake pipe corroded, covered in grease or other material slightly swollen beneath paint (1.1.11 (c))

Fail Offside Rear Parking brake inoperative on one side (1.4.1 (a))

Advice Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

Fail Front Windscreen washer not working (3.5 (a))

Advice Brake pipe corroded, covered in grease or other material front to rear slightly swollen beneath paint (1.1.11 (c))

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

Advice Oil leak, but not excessive gearbox (8.4.1 (a) (i))

MOT #7

2018-07-03 15:50

MOT test number

374334106036

Result**✓ Passed**

Advice Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (i))

**MOT #6** 2018-07-02 13:38**MOT test number** 955021095475**Result** ✗ Failed

- Fail** Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Front Exhaust has a major leak of exhaust gases weld at cat to front pipe (6.1.2 (a))
- Advice** Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (i))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #5 2017-06-30 15:33**MOT test number** 997793035855**Result** ✓ Passed

- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Front brake fluctuating, but not excessively Discs in poor condition (3.7.B.3)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #4 2016-03-18 10:32**MOT test number** 855379855531**Result** ✓ Passed**MOT #3** 2015-03-19 17:27**MOT test number** 828868175005**Result** ✓ Passed



MOT #2	2014-02-20 10:58
MOT test number	178931954056
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components

MOT #1	2013-02-28 14:48
MOT test number	265049053019
Result	✓ Passed
Advice	Rear Exhaust has a minor leak of exhaust gases (7.1.2)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
22 June 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	22 June 2024
Full MOT history	See MOT history

Tax calculation


Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	SC59KKB
Plate since	2024-03-28
Current registration	SC59KKB
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-02-26
Last registration	2023-06-23
Complete history	See info



Registration #1	2010-02-26	9 mi
Registration #2	2013-02-28	20.281 mi
Registration #3	2014-02-20	26.327 mi
Registration #4	2015-03-19	32.960 mi
Registration #5	2016-03-18	38.710 mi
Registration #6	2017-06-30	44.109 mi
Registration #7	2018-07-02	48.189 mi
Registration #8	2018-07-03	48.189 mi
Registration #9	2019-07-02	52.703 mi
Registration #10	2020-06-23	55.377 mi
Registration #11	2021-06-23	55.377 mi
Registration #12	2022-06-23	55.377 mi
Registration #13	2023-06-23	55.377 mi
Registration #14	2024-03-28	55.377 mi
Registration #15	2024-03-28	55.377 mi
Registration #16	2024-03-28	55.377 mi
Registration #17	2024-03-28	55.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1260 kg
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1402593